

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/16/2019

Submitted Date:

12/16/2019

Document Number:

699100749**FIELD INSPECTION FORM**

Loc ID 331510 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_

**Operator Information:**OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**16 Number of Comments3 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**

**Contact Information:**

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
423119	WELL	SI	09/01/2019	OW	123-33502	CARMIN USX CC05-23D	TA
423121	WELL	SI	09/01/2019	OW	123-33503	CARMIN USX CC05-10D	TA
423128	WELL	SI	04/01/2019	OW	123-33505	CARMIN USX CC05-16D	TA
423145	WELL	SI	09/01/2019	OW	123-33511	CARMIN USX CC05-17D	SI

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: \_\_\_\_\_

**Good Housekeeping:**

Type	TRASH		
Comment:	Trash around well needs to be removed for good housekeeping. See attached photo.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/22/2020

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 4		
Comment: <a href="#">Appear to be plumbed to surface.</a>			
Corrective Action:		Date:	
Type: Gas Meter Run	# 2		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 2		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Bird Protectors	# 5		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	STEEL AST		40.335410,-104.453140
Comment:					
Corrective Action:					Date:

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Inadequate	Walls Insufficient	Base Sufficient	Inadequate	
Comment: <a href="#">Inadequate berms around produced water tank.</a>					
Corrective Action: <a href="#">Repair or install berms or other secondary containment devices per Rule 906.d.(1).</a>				Date: <u>01/22/2020</u>	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	3	OTHER	BV CONCRETE		,
Comment: <a href="#">Shares containment with crude oil tanks.</a>					
Corrective Action:					Date:

**Paint**

Condition	
Other (Content)	
Other (Capacity)	60 BBL
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	3	300 BBLs	STEEL AST		40.335470,-104.453140
Comment:	South Crude tank has a faded Capacity label and Middle crude tank is missing Capacity label.				
Corrective Action:	Install sign to comply with Rule 210.d.				Date: 01/22/2020

**Paint**

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

**Venting:**

Yes/No	NO
Comment:	
Corrective Action:	Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

**Inspected Facilities**

Facility ID: 423119 Type: WELL API Number: 123-33502 Status: SI Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: T/A, Has Blue "T/A" Variance Tag

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 423121 Type: WELL API Number: 123-33503 Status: SI Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: T/A, Has Blue "T/A" Variance Tag

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 423128 Type: WELL API Number: 123-33505 Status: SI Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: T/A, Has Blue "T/A" Variance Tag

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

Facility ID: 423145 Type: WELL API Number: 123-33511 Status: SI Insp. Status: SI

**Idle Well**

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: \_\_\_\_\_

Comment: SI

Corrective Action: \_\_\_\_\_ Date: \_\_\_\_\_

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 12/16/19 at approximately 0954 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at Carmin USX CC 05-17D of Noble Energy, at Location ID: 331510 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>South Crude tank has a faded Capacity label and Middle crude tank is missing Capacity label. Install sign to comply with Rule 210.d. With a corrective date of 1/22/20.</p> <p>Inadequate berms around produced water tank. Repair or install berms or other secondary containment devices per Rule 906.d.(1). With a corrective date of 1/22/20.</p> <p>Trash around well needs to be removed for good housekeeping. Comply with Rule 603.f . With a corrective date of 1/22/20.</p> <p>See attached photos</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education inspections</p>	burnsa	12/16/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699100750	Inspection Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5014374">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5014374</a>