

# Interim Reclamation and Stormwater Inspection

December 11, 2019

Operator: SRC ENERGY INC- #10311

Location ID: 332974

Inspection Document #: 697500912

Weld County, CO

NWSW Section 4 T5N R66W

Chris Binschus  
Reclamation Specialist, COGCC



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

Inspection Photos  
Location Name: DUKE USX J  
Location ID: 332974



**Photo 1.** Photo taken from the location, facing East. Operator has perform interim reclamation to reduce disturbance areas only needed for production operations. At the time of this inspection, there was no stormwater erosion observed. At the time of this inspection, snow cover prevented COGCC staff from performing a vegetative assessment. COGCC staff will perform a follow up inspection to ensure compliance with Rule 1003 standards.

Inspection Photos  
Location Name: DUKE USX J  
Location ID: 332974



**Photo 2.** Photo taken from the central location, facing East. See comments under Photo 1.

Inspection Photos  
Location Name: DUKE USX J  
Location ID: 332974



**Photo 3.** Photo taken from the central location, facing West. See comments under Photo 1.

Inspection Photos  
Location Name: DUKE USX J  
Location ID: 332974



**Photo 4.** Photo taken from the central location, facing Northwest. See comments under Photo 1.