

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			Date:
Corrective Action:			
Good Housekeeping:			
Type	OTHER		
Comment:	Stained soil by flow line valve from WH		
Corrective Action:	Properly treat or dispose of oily waste in accordance with 907.e		Date: 11/23/2019
Type	OTHER		
Comment:	Possible leak on flow line valve coming from WH.		
Corrective Action:	Rule 605.d: Securely fasten all valves, pipes, and fittings to ensure good mechanical condition, inspect at regular intervals and maintain in good mechanical condition.		Date: 11/23/2019
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	PUMP JACK		
Comment:	Steel pipe angla iron		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Barbwire		
Corrective Action:			Date:
Equipment:			
Type: Bradenhead # 1			corrective date
Comment:	Appears to be plumbed to surface		
Corrective Action:			Date:
Type: Pump Jack # 1			
Comment:			
Corrective Action:			Date:
Type: Prime Mover # 1			
Comment:	Electric motor		
Corrective Action:			Date:

Type: Ancillary equipment	# 1	
Comment:	Electric panel, transformers and meter box	
Corrective Action:		Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 241291 Type: WELL API Number: 123-09079 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>On Monday 12/16/2019 at approximately 0950 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a KP Kaufman location: Perrin-Mahoney #2 at API #05-123-09079 in Weld County Colorado. While there, I observed a Shut in wellsite. This is a follow up inspection per Doc. # 699300545. During this inspection the following compliance issues were observed and are now delinquent: Rule 907.e: Stained soil by Flow line valve coming off WH. CA date 11/23/2019 see photos 3 & 4. Rule 605.d Mechanical issue: Possible leak on flow line valve coming from WH. CA date 11/23/2019 see photo 4. Location is dry, weather is partly cloudy. This inspection is being submitted to enforcement due to non compliance with COGCC Rules. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	12/16/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300743	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5014639