

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/16/2019

Submitted Date:

12/16/2019

Document Number:

699300744

FIELD INSPECTION FORM
 Loc ID 317951 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 46290

Name of Operator: KP KAUFFMAN COMPANY INC

Address: 1675 BROADWAY, STE 2800

City: DENVER State: CO Zip: 80202

Status Summary:

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

14 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
240242	WELL	SI	06/01/2019	OW	123-08030	MAHONEY-PERRIN 1	SI

General Comment:

LocationOverall Good: ☒

Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Adequate		
Corrective Action:		Date:	
Type	BATTERY		
Comment:	Adequate		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Unused flow line risers have been marked		
Corrective Action:	Comply with Rule 603.f For unused, unmarked flow line risers 24 hrs. to lock out tag out. 30 days to remove riser.	Date:	09/30/2019

Overall Good: ☐

Spills:			
Type	Area	Volume	

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type	WELLHEAD		
Comment:	barb wire		
Corrective Action:		Date:	
Type	PUMP JACK		
Comment:	steel pipe		
Corrective Action:		Date:	
Type	OTHER		
Comment:	Electrical transformers, breaker panel and meter. Barb wire		
Corrective Action:		Date:	

Equipment:

Type: Horizontal Heated Separator	# 1		corrective date
Comment:			
Corrective Action:		Date:	

Type: Pump Jack	# 1	
Comment:		
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment: Electric motor		
Corrective Action:		Date:
Type: Emission Control Device	# 1	
Comment:		
Corrective Action:		Date:
Type: Ancillary equipment	# 1	
Comment: Electrical transformers, breaker panel and meter.		
Corrective Action:		Date:
Type: Bradenhead	# 1	
Comment: Appears to be plumbed to surface		
Corrective Action:		Date:
Type: Bird Protectors	# 2	
Comment:		
Corrective Action:		Date:
Type: Compressor	# 1	
Comment:		
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	300 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:				Date:	
Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLS	STEEL AST		,
Comment:					
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Shares containmnet with crude oil tank			
Corrective Action:			Date:	

Venting:

Yes/No	NO		
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 240242 Type: WELL API Number: 123-08030 Status: SI Insp. Status: SI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____

Comment: SI

Corrective Action: _____ Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Monday 12/16/19 at approximately 11:00 am, I, Inspector Robbie Revas, conducted an on-site inspection at The Mahoney-Perrin #1 KP Kauffman location at API #05-123-08030 in Weld County Colorado.</p> <p>While there, I observed a Shut in well and tank battery. This is a follow up inspection per Doc. # 699300059</p> <p>During this inspection the following compliance issues appear to have addressed:</p> <p>907.e Stained soil around WH appears to have been removed See photos #2 & 4.</p> <p>907.e Stained soil a PJ base appear to have been removed See photo #5.</p> <p>603.f Weeds growing on location appear to have been removed See photo # 3</p> <p>907.e Stained soil in Compressor shed appears to have been removed see photo #12</p> <p>605.d Mechanical issue: hammer union with possible leak appears to have been tightened. See photo 13</p> <p>603.f Trash: Unused material corrugated tin on location appears to have been removed see photo 10</p> <p>603.fTrash: unused material in compressor shed appears to have been removed. See photo # 12</p> <p>During this inspection the following compliance issues appear to have been partially addressed and is delinquent:</p> <p>Unmarked flow line risers:Risers have been marked but not LOTO or removed Rule 603.f 24 hrs. to LOTO</p> <p>30 days to remove riser CA date 9/30/2019. See photos 7 & 8.</p> <p>Location is dry and weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary Inspection.</p> <p>This is a summary of inspection report.</p>	revasr	12/16/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699300745	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5014640