

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2019

Submitted Date:

12/10/2019

Document Number:

687905886

FIELD INSPECTION FORMLoc ID 325570 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 10000

Name of Operator: BP AMERICA PRODUCTION COMPANY

Address: 1199 MAIN AVENUE SUITE 101

City: DURANGO State: CO Zip: 81301

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

19 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Beebe, Sabre	970-779-9398	Sabre.Beebe@bpx.com	SW Inspection Reports
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Inspections, All		SanJuanCOGCC@bp.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
215021	WELL	SI	03/01/2018	GW	067-06626	CUNDIFF 34-01 1	SI

General Comment:[Site inspection and equipment inventory with photos at the end of this report.](#)

Location				
Lease Road:				
Type	Access			
comment:	Gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Signs/Marker:				
Type	WELLHEAD			
Comment:	Sign posted at main entrance gate at county road before entrance to location.			
Corrective Action:				Date:
Type	TANK LABELS/PLACARDS			
Comment:	Labels and placards posted on tank.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on sign.			
Corrective Action:				Date: _____
Good Housekeeping:				
Type	UNUSED EQUIPMENT			
Comment:	Unused sound panels laying off corner of wellpad are unused equipment.			
Corrective Action:	Remove unused equipment per Rule 603.f.			Date: 01/10/2020
Overall Good: <input type="checkbox"/>				
Spills:				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
Fencing/:				
Type	SEPARATOR			
Comment:	Cattle panels around separator and meter house.			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Cattle panels around wellhead and pumpjack.			
Corrective Action:				Date:
Equipment:				
Type: Pump Jack	# 1			corrective date
Comment:				
Corrective Action:				Date:
Type: Vertical Heated Separator	# 1			
Comment:				

Corrective Action:		Date:	
Type: Bird Protectors	# 1		
Comment:	On separator stack.		
Corrective Action:		Date:	
Type: Flow Line	# 5		
Comment:	1-3" flowline from wellhead to separator. 1-1" flowline from separator to pumpjack engine fuel gas. 1-2" flowline from separator dump valve to produced water tank. 1-2" flowline from separator to meter house. 1-2" flowline from meter house to offsite dogleg.		
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with block valve assembly installed.		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	PVC bradenhead access.		
Corrective Action:		Date:	
Type: Prime Mover	# 1		
Comment:	Natural gas engine installed on pumping unit.		
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	<100 BBLS	PBV STEEL		,
Comment:	95 BBL tank.				
Corrective Action:					Date:

Paint

Condition	Adequate
Other (Content)	
Other (Capacity)	
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:				
Corrective Action:				Date:

Venting:

Yes/No	NO
Comment:	
Corrective Action:	Date:

Flaring:			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected FacilitiesFacility ID: 215021 Type: WELL API Number: 067-06626 Status: SI Insp. Status: SI**Idle Well**Purpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Well shut-in as of March/2018. Bradenhead test conducted on 7/27/17 Doc# 2528674

Corrective Action: _____ Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Ditches	Pass	Ditches	Pass			
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			
				Material Handling And Spill Prevention	Pass	Spill prevention for engine oil tank.
Gravel	Pass					

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402259723	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5009964
687905887	Overview photo looking North.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5009960
687905888	Unused equipment SE corner of location.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5009961