

Location

Overall Good:

Signs/Marker:

Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:		Date:	
Corrective Action:			

Good Housekeeping:

Type	UNUSED EQUIPMENT		
Comment:	Production lines have been removed for Horz. prep		
Corrective Action:	Comply with Rule 603.f	Date:	12/25/2019

Overall Good:

Spills:

Type	Area	Volume		

In Containment: No

Comment:

Multiple Spills and Releases?

Fencing/:

Type	WELLHEAD		
Comment:	AG fence		
Corrective Action:		Date:	

Equipment:

Type	Quantity	Comment	Corrective Action	Date	corrective date
Ancillary equipment	# 1	Electric panel transformers and meter box			
Prime Mover	# 1	Electric motor			
Pump Jack	# 1				
Bradenhead	# 2	Appear to be plumbed to surface			

Venting:

Yes/No	NO		
Comment:			

Corrective Action:		Date:	
--------------------	--	-------	--

Flaring:

Type			
Comment:			
Corrective Action:		Date:	

Inspected Facilities

Facility ID: 265009 Type: WELL API Number: 123-21137 Status: SI Insp. Status: SI

Idle Well

Purpose: Shut In Temporarily Abandoned Reminder: _____

Comment:

Corrective Action: Date: _____

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary On Tuesday 12/10/2019 at approximately 1230 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location: Mleynek #28-10 JI at API #05-123-21137 in Weld County Colorado. While there, I observed a shut in wellsite. During this inspection the following possible compliance issues were observed: Housekeeping 603.f: Unused equipment on location due to horz.prep. CA date 12-25-2019 see photo 2. Location is wet & muddy, weather is partly cloudy. A follow up on this site inspection needs to be conducted to ensure the Compliance issues have been corrected to comply with COGCC rules. Continuing education COGCC Inspection Report Summary. This is a summary of inspection report.</p>	revasr	12/10/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402259831	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5010119
699300707	Location pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5010109