

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-08335
Date: 12-13-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Revegetation is failed here as only observed vegetation is comprised of weeds such as kochia and field bindweed.



Photo 3. View of the northern project area from the northwestern corner facing eastward. Revegetation is failed here, as observable vegetation is comprised of kochia and field bindweed.



Photo 4. View of the western project area from the southwestern corner facing northward. Wattles are full of sediment and do not appear to be functioning.



Photo 5. View of Canada thistles growing within the northwestern project area.



Photo 6. View of reference area, comprised of irrigated grass field.