

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/05/2019

Submitted Date:

12/17/2019

Document Number:

693200470

FIELD INSPECTION FORMLoc ID 315114 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**

OGCC Operator Number: 74740

Name of Operator: RIO MESA RESOURCES INC

Address: P.O. BOX 984

City: RANGELY State: CO Zip: 81648

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments

1 Number of Corrective Actions

☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Producing well Engineering Integrity Supervisor
Whittington, Ellice		ellice.whittington@state.co.us	
Hayes, Mike	970-620-2257	hayespetro@centurytel.net	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
230276	WELL	PR	05/30/2002	OW	103-07935	GOVERNMENT 6-2X	EG

General Comment:

Engineering Integrity Inspection performed on December 5, 2019

Inspected FacilitiesFacility ID: 230276 Type: WELL API Number: 103-07935 Status: PR Insp. Status: EG**Flowline**

#1	Type: Non-Well Site	of Lines	
----	---------------------	----------	--

Flowline Description

Flowline Type: Non-Well Site Size: Material:

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: The off location flowline (wellhead line) runs approximately 300' N from the wellhead to facility/ battery. Flowline services 2 wells in area. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44. Note: Operator has not registered any off location flowlines with COGCC; Corrective Action outlined may be applicable to additional wells operated by RIO MESA RESOURCES INC

Corrective Action: Operator shall comply with the following COGCC rule: 1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off-location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.

Date: 10/31/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
693200478	rio mesa	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015141