

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/17/2019

Submitted Date:

12/17/2019

Document Number:

699500409

FIELD INSPECTION FORM
 Loc ID 444280 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 47120

Name of Operator: KERR MCGEE OIL & GAS ONSHORE LP

Address: P O BOX 173779

City: DENVER State: CO Zip: 80217-

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:

5 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
444275	WELL	PR	09/01/2018	OW	123-42537	MEESE 1C-14HZ	PR
444276	WELL	PR	06/01/2019	OW	123-42538	MEESE STATE 38C-35HZ	PR
444277	WELL	PR	08/10/2017	OW	123-42539	MEESE 37C-35HZ	PR
444278	WELL	PR	08/02/2017	OW	123-42540	MEESE 16N-35HZ	PR
444279	WELL	PR	06/01/2019	OW	123-42541	MEESE 26N-14HZ	PR
444281	WELL	PR	10/01/2018	OW	123-42542	MEESE 1N-14HZ	PR
444282	WELL	PR	08/03/2017	OW	123-42543	MEESE 27N-14HZ	PR
444283	WELL	PR	08/09/2017	OW	123-42544	MEESE STATE 38N-35HZ	PR

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Bradenhead

8

Comment:

Corrective Action:

Date:

Type: Ancillary equipment

12

Comment: automation

Corrective Action:

Date:

Type: Plunger Lift

8

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected FacilitiesFacility ID: 444275 Type: WELL API Number: 123-42537 Status: PR Insp. Status: PRFacility ID: 444276 Type: WELL API Number: 123-42538 Status: PR Insp. Status: PRFacility ID: 444277 Type: WELL API Number: 123-42539 Status: PR Insp. Status: PRFacility ID: 444278 Type: WELL API Number: 123-42540 Status: PR Insp. Status: PRFacility ID: 444279 Type: WELL API Number: 123-42541 Status: PR Insp. Status: PRFacility ID: 444281 Type: WELL API Number: 123-42542 Status: PR Insp. Status: PRFacility ID: 444282 Type: WELL API Number: 123-42543 Status: PR Insp. Status: PRFacility ID: 444283 Type: WELL API Number: 123-42544 Status: PR Insp. Status: PR**Producing Well**Comment: PR

Corrective Action:

Date:

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of location may have been distorted due to weather conditions.	medinaj	12/17/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500410	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015345