

Inspection Photos

Operator: Hilcorp Energy
Location/API #: 067-06118
Date: 12-13-2019



Photo 1. View of the project area from the northern corner facing center.



Photo 2. View of the northwestern project area from the northern corner facing northeastward. Observable vegetation is musk thistle and Russian thistle plants (weeds).



Photo 3. View of diversion and bare soils within the northwestern project area that are not stabilized.



Photo 4. View of area downslope from diversion in Photo 3, where sediment is discharging off of the project area.



Photo 5. View of rilling and bare soils within the southwestern project area needing stabilization.



Photo 6. View of southwestern project area from the western corner facing southeastward. Soils are bare with little to no desirable vegetation.



Photo 7. View of reference area, comprised of an irrigated grass field.