

**Inspection Photos**  
**Operator: BP America**  
**Location/API #: 067-06664**  
**Date: 12-13-2019**



Photo 1. View of the project area from the western edge facing center.



Photo 2. View of the northern project area from the northwestern corner facing eastward. Revegetation is progressing within this portion of the reclamation area with grasses such as smooth brome, in a dormant vegetative condition.



Photo 3. View of the western project area from the northwestern corner facing southward. Revegetation is progressing on the lower portion of the slope, but is sparse and not progressing on the fill slope. Weedy kochia and Russian thistle debris is present.



Photo 4. View of area in the western fill slope where revegetation is failed and revegetation/stabilization measures are needed.



Photo 7. View of Russian thistle up to 3 feet tall near the well pad entrance.



Photo 7. View of reference area north of the project area, comprised of an irrigated grass field.