

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/16/2019

Submitted Date:

12/18/2019

Document Number:

690101592**FIELD INSPECTION FORM**Loc ID \_\_\_\_\_ Inspector Name: \_\_\_\_\_ On-Site Inspection ☐  
Maclaren, Joe 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**2 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Mickelson, Erik		Erik_Mickelson@oxy.com	
Gintautas, Peter		peter.gintautas@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
		cogccinspections@anadarko.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
469883	SPILL OR RELEASE	AC	12/14/2019		-	Camp 13-19A	EG

**General Comment:**

Engineering Integrity Field Inspection performed on December 16th, 2019 in response to initial form 19 spill report Doc #402260584 received by COGCC on 12/13/2019 that outlines: During dump line removal activities associated with the Camp 13-19A facility, historical petroleum hydrocarbon impacts to the subsurface were encountered. The volume of the release is unknown.

Details of observations made during this field inspection are located in the flowline section of this report. Photos uploaded.

**Inspected Facilities**Facility ID: 469883 Type: SPILL OR API Number: - Status: AC Insp. Status: EG**Flowline**

#1	Type: Dump Line	of Lines	
----	-----------------	----------	--

Flowline Description

Flowline Type: Dump Line Size: Material:

Variance: Age: Contents:

Integrity Summary

Failures: Spills: Repairs Made:

Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules (check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☒ 1103. Abandonment

Comment: COGCC Inspector met with Anadarko contract personnel (NG Services) on location. The Camp 13-19A facility/ battery is being decommissioned/ equipment removed; the dump flowlines and process pipe associated with the old battery are being removed. Contractors uncovered several historically abandoned dump lines and are in the process of removing these flowlines. The original Camp 13-19A on location wellhead flowline was also removed; a new on location flowline has been constructed and routed north to a shared facility/ battery. This flowline was pressure tested (prior to being put into service). Contractors were completing excavation/ remediation work at the time of this field inspection.

Corrective Action: Date:

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
690101599	Wellhead (LOTO) and signage	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5016466">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5016466</a>
690101601	Excavation (groundwater); dump lines being removed	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5016467">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5016467</a>
690101603	Flowline manifold; Camp 13-19A tie in at separator	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5016468">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5016468</a>