

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2019

Submitted Date:

12/18/2019

Document Number:

696101706

**FIELD INSPECTION FORM**Loc ID 331381 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

6 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
MacLaren, Joe		joe.maclaren@state.co.us	
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
,		EHSRC@bonanzacrk.com	All Inspections

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
261350	WELL	PA	06/19/2019	GW	123-20594	DOW 43-28	PA
435361	TANK BATTERY	AC	12/09/2013	LO	-	DOW 43-28 Tank Battery 435361	PA

**General Comment:**

This is a PLUGGED & ABANDONED WELL & BATTERY inspection.  
 Well(s): 1: Plugged & Abandoned | PA.  
 Battery: Abandoned. ALL equipment removed.  
 Reclamation progressing.  
 Abandoned Battery SE corner GPS coordinates: 40.368570, -104.433240.  
 Follow-up to Field Inspection Report doc. #696101582 dated 11/19/2019.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L	Date:		
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date:
Corrective Action:				
<b>Good Housekeeping:</b>				
Type	UNUSED EQUIPMENT			
Comment:	<p>Prior insp:            Unused equipment (Gas meter run) at Abandoned Battery site.            Refer to Rule 603.f.            Remove unused equipment (Gas meter run) at Abandoned Battery site.            Comply w/ Rule 603.f.            Corrective Action date: 12/20/2019.</p> <p>This insp:            * Unused equipment (Gas meter run) at Abandoned Battery site. NOW removed.            See photos #1, 2.</p>			
Corrective Action:				Date:
Type	TRASH			
Comment:	<p>Prior insp:            Trash &amp; Junk (Cut casing pipe, cement chunks, plastic liner) at Plugged &amp; Abandoned   PA wellsite.            Refer to Rule 603.f.            Remove Trash &amp; Junk (Cut casing pipe, cement chunks, plastic liner) at Plugged &amp; Abandoned   PA wellsite.            Comply w/ Rule 603.f.            Corrective Action date: 11/27/2019.</p> <p>This insp:            * Trash &amp; Junk (Cut casing pipe, cement chunks, plastic liner) at Plugged &amp; Abandoned   PA wellsite. NOW removed.            See photos #3, 4.</p>			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment: <div style="border: 1px solid black; height: 20px; width: 100%;"></div>				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Venting:</b>				
Yes/No				
Comment:				
Corrective Action:				Date:

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

--	--	--	--

Inspected Facilities									
Facility ID:	261350	Type:	WELL	API Number:	123-20594	Status:	PA	Insp. Status:	PA
Facility ID:	435361	Type:	TANK	API Number:	-	Status:	AC	Insp. Status:	PA

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 12/18/2019 at approximately 10:26 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: DOW-65N63W /28NESE  Location ID: 331381  Well Name: DOW 43-28  API: 05-123-20594  Location County: Weld County, Colorado  Weather: Partly cloudy w/ partial snow coverage from prior storm.</p> <p>While there, I observed:  Well(s): 1: Plugged &amp; Abandoned   PA.  Battery: Abandoned. ALL equipment removed.  Reclamation progressing.</p> <p>Abandoned Battery SE corner GPS coordinates: 40.368570, -104.433240.</p> <p>Follow-up to Field Inspection Report doc. #696101582 dated 11/19/2019.  During this inspection, the following prior possible compliance issues appear to be addressed:  1.) Unused equipment (Gas meter run) at Abandoned Battery site.  Refer to Rule 603.f.  Remove unused equipment (Gas meter run) at Abandoned Battery site.  Comply w/ Rule 603.f.  Corrective Action date: 12/20/2019.  * Unused equipment (Gas meter run) at Abandoned Battery site. NOW removed.  See photos #1, 2.</p> <p>2.) Trash &amp; Junk (Cut casing pipe, cement chunks, plastic liner) at Plugged &amp; Abandoned   PA wellsite.  Refer to Rule 603.f.  Remove Trash &amp; Junk (Cut casing pipe, cement chunks, plastic liner) at Plugged &amp; Abandoned   PA wellsite.  Comply w/ Rule 603.f.  Corrective Action date: 11/27/2019.  * Trash &amp; Junk (Cut casing pipe, cement chunks, plastic liner) at Plugged &amp; Abandoned   PA wellsite. NOW removed.  See photos #3, 4.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/18/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101707	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5016854">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5016854</a>