

Inspection Photos

Operator: Enduring Resources
Location/API #: 067-06564
Date: 12-18-2019



Photo 1. View of the project area from the northeastern edge facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Location is largely snow covered at this time. A mix of perennial grass species such as crested wheatgrass and annual weeds such as prickly lettuce are observable through the snow.



Photo 3. View of musk thistles in post-flowering condition. Approximately 30 individuals observed.



Photo 4. View of reference area, comprised of a grass field. Cattle were present at the time of the inspection.