

**Inspection Photos**  
**Operator: Hilcorp Energy**  
**Location/API #: 067-08147**  
**Date: 12-18-2019**



Photo 1. View of the project area from the southwestern edge facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Location is partially snow covered at this time. Revegetation is in a dormant vegetative condition, and largely comprised of intermediate wheatgrass.



Photo 3. View of reference area, comprised of a grass field in dormant vegetative condition.