

Inspection Photos

Operator: Hilcorp Energy
Location/API #: 067-08202
Date: 12-18-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the northeastern corner facing southward. Location is partially snow covered at this time. Revegetation is in a dormant vegetative condition, and largely comprised of smooth brome, rubber rabbitbrush, and sand dropseed.



Photo 3. View of musk thistles in a post-flowering condition within the interim reclamation area.



Photo 4. View of reference area, comprised of an irrigated grass field in dormant vegetative condition.