

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2019

Submitted Date:

12/19/2019

Document Number:

696101710

**FIELD INSPECTION FORM**Loc ID 305671 Inspector Name: Evins, Bret On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**

OGCC Operator Number: 8960

Name of Operator: BONANZA CREEK ENERGY OPERATING COMPANY

Address: 410 17TH STREET SUITE #1400

City: DENVER State: CO Zip: 80202

**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

13 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		EHSRC@bonanzacrk.com	All Inspections
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
280955	WELL	PA	07/03/2019	GW	123-23332	LAURA 8-28	PA
447085	TANK BATTERY	AC	07/29/2016		-	LAURA-65N63W 28SENE	PA
447086	TANK BATTERY	AC	07/29/2016		-	LAURA-65N63W 28SENE	PA

**General Comment:**

This is a PLUGGED &amp; ABANDONED WELL &amp; BATTERY inspection.

Well(s): 1: Plugged &amp; Abandoned | PA.

Battery: Abandoned. ALL equipment removed.

Reclamation progressing.

Abandoned Battery SE corner GPS coordinates: 40.372510, -104.433274.

Follow-up to Field Inspection Report doc. #696101584 dated 11/19/2019.

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Adequate			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
Emergency Contact Number:				
Comment:				Date:
Corrective Action:				Date:
<b>Good Housekeeping:</b>				
Type	UNUSED EQUIPMENT			
Comment:	<p>Prior insp:            Unused equipment (Gas meter run) at Abandoned Battery site.            Refer to Rule 603.f.            Remove unused equipment (Gas meter run) at Abandoned Battery site.            Comply w/ Rule 603.f.            Corrective Action date: 12/20/2019.</p> <p>This insp:            * Unused equipment (Gas meter run) at Abandoned Battery site. NOW removed.            See photos #1, 2.</p>			
Corrective Action:				Date:
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Equipment:</b>				
Type: Horizontal Heated Separator	# 0			corrective date
Comment:	Plugged & Abandoned   PA well & Abandoned battery site.			
Corrective Action:				Date:
Type: Pig Station	# 0			
Comment:	Plugged & Abandoned   PA well & Abandoned battery site.			
Corrective Action:				Date:
Type: Plunger Lift	# 0			
Comment:	Plugged & Abandoned   PA well & Abandoned battery site.			
Corrective Action:				Date:
Type: Emission Control Device	# 0			
Comment:	Plugged & Abandoned   PA well & Abandoned battery site.			
Corrective Action:				Date:
Type: Gas Meter Run	# 0			

Comment:	Plugged & Abandoned   PA well & Abandoned battery site.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	0				,	
Comment:	Plugged & Abandoned   PA well & Abandoned battery site.					
Corrective Action:						Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment:	Plugged & Abandoned   PA well & Abandoned battery site.					
Corrective Action:						Date:

**Paint**

Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

**Venting:**

Yes/No			
Comment:			
Corrective Action:		Date:	

**Flaring:**

Type		
Comment:		
Corrective Action:		Date:

**Inspected Facilities**Facility ID: 280955 Type: WELL API Number: 123-23332 Status: PA Insp. Status: PA**Workover**

Comment: Plugged & Abandoned | PA.  
Casing appears to be cut / capped.  
Form 6 doc. #402100593 indicates cut & cap date: 06/26/2019. Approved

Corrective Action: Date: Facility ID: 447085 Type: TANK API Number: - Status: AC Insp. Status: PAFacility ID: 447086 Type: TANK API Number: - Status: AC Insp. Status: PA

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel		Gravel				

Comment: Corrective Action: Date: **Pits:** ☐ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
<p><b>COGCC Inspection Report Summary:</b></p> <p>On WED 12/18/2019 at approximately 10:58 hrs. I, Bret Evins, conducted an on-site inspection at:  Operator Name: BONANZA CREEK ENERGY OPERATING COMPANY LLC  Location Name: LAURA-65N63W /28SENE  Location ID: 305671  Well Name: Laura 8-28  API: 05-123-23332  Location County: Weld County, Colorado  Weather: Partly cloudy w/ partial snow coverage from prior storm.</p> <p>While there, I observed:  Well(s): 1: Plugged &amp; Abandoned   PA.  Battery: Abandoned. ALL equipment removed.  Reclamation progressing.</p> <p>Abandoned Battery SE corner GPS coordinates: 40.372510, -104.433274.</p> <p>Follow-up to Field Inspection Report doc. #696101584 dated 11/19/2019.  During this inspection, the following prior possible compliance issues appear to be addressed:  1.) Unused equipment (Gas meter run) at Abandoned Battery site.  Refer to Rule 603.f.  Remove unused equipment (Gas meter run) at Abandoned Battery site.  Comply w/ Rule 603.f.  Corrective Action date: 12/20/2019.  * Unused equipment (Gas meter run) at Abandoned Battery site. NOW removed.  See photos #1, 2.</p> <p>During this inspection, NO New/Current possible compliance issues were observed.</p> <p>This is a summary of the inspection report.</p>	evinsb	12/19/2019

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
696101711	Site photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017751">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017751</a>