

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-07580
Date: 12-18-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Location is largely snow covered at this time. Revegetation is in a dormant vegetative condition, and largely comprised of smooth brome.



Photo 3. View of reference area, comprised of an irrigated grass field in dormant vegetative condition.