

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-07787
Date: 12-18-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the western fill slope from the southwestern corner facing northward. Location is partially snow covered at this time. Revegetation is in a dormant vegetative condition, and largely comprised of smooth brome, western wheatgrass, and sand dropseed.



Photo 3. View of the southern project area from the southwestern corner facing eastward.



Photo 4. View of reference area, comprised grass field, largely comprised of smooth brome, in dormant vegetative condition.