

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-07929
Date: 12-18-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Location is partially snow covered at this time. Revegetation is in a dormant vegetative condition, and largely comprised of smooth brome, western wheatgrass, and sand dropseed. Junk, debris, and unused equipment stored within the eastern project area.



Photo 3. View of unused equipment, junk, and debris in the eastern project area, needs to be removed.



Photo 4. View of reference area comprised grass field, largely comprised of smooth brome in dormant vegetative condition.