

Inspection Photos
Operator: Enduring Resources
Location/API #: 067-07762
Date: 12-18-2019



Photo 1. View of the project area from the southeastern corner facing center.



Photo 2. View of the eastern fill slope from the southeastern corner facing northward. Revegetation is progressing in this area with grasses such as western wheatgrass and crested wheatgrass.



Photo 3. View of reference area comprised of irrigation grass field that is largely snow covered at this time.