

FORM
INSPRev
X/15

State of Colorado Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2019

Submitted Date:

12/19/2019

Document Number:

687905938

FIELD INSPECTION FORM

Loc ID 325159 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87415

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:

21 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	SW Inspection Reports.
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Sessions, Tamara	505-324-4145	tsessions@logosresourcesllc.com	SW Inspection Reports

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
214159	WELL	PR	09/01/2019	GW	067-05476	IGNACIO 33-8 5	PR

General Comment:

[Site inspection and equipment inventory with photos at the end of this report.](#)

Location			
Lease Road:			
Type	Access		
comment:	Gravel access road with location on edge of road.		
Corrective ActionL			Date:
Overall Good: <input type="checkbox"/>			
Signs/Marker:			
Type	TANK LABELS/PLACARDS		
Comment:	Labels and placards posted on sign on PBV fence.		
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Sign posted on meter house at location.		
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	Contact information posted on signs.		
Corrective Action:			Date: _____
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	T-post and hogwire around PBV.		
Corrective Action:			Date:
Equipment:			
Type: Ancillary equipment	# 1		corrective date
Comment:	Rectifier located on edge of location.		
Corrective Action:			Date:
Type: Flow Line	# 8		
Comment:	2-2" steel flowlines from wellhead to separators. 2-1" steel flowlines from separator dump valves to produced water tank. 2-2" steel flowlines from separator becoming 2-4" flowlines to meter houses. 2-4" flowlines from meter houses to sales line valve riser on location. All points co-located and are in use.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Wellhead with dual block valve assembly producing out of (2) different formations (MV, DK).		
Corrective Action:			Date:
Type: Gas Meter Run	# 2		

Comment:	Dual gas meters on location producing from separate formations (MV, DK)		Date:	
Corrective Action:			Date:	
Type: Bradenhead	# 1			
Comment:	Plumbed to surface.		Date:	
Corrective Action:			Date:	
Type: Bird Protectors	# 2			
Comment:	On both separator stacks.		Date:	
Corrective Action:			Date:	
Type: Ancillary equipment	# 1			
Comment:	Telemetry equipment installed on meter house.		Date:	
Corrective Action:			Date:	
Type: Horizontal Heated Separator	# 2			
Comment:	Separators producing from (2) different formations (MV, DK)		Date:	
Corrective Action:			Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV STEEL		
Comment:	125 BBL tank with expanded metal screen.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Compacted gravel berm around PBV.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 214159 Type: WELL API Number: 067-05476 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing out of \(2\) different formations \(MV, DK\)](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass					
Compaction	Pass	Gravel	Pass			
Berms	Pass	Compaction	Pass			

Comment: Stormwater berm along southern edge of location. Stormwater BMP's appear to be functioning at time of inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905939	Overview photo looking East.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5018331