

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2019

Submitted Date:

12/19/2019

Document Number:

687905943

FIELD INSPECTION FORM

Loc ID 326543 Inspector Name: Stewart, Joseph On-Site Inspection 2A Doc Num: _____

Operator Information:
OGCC Operator Number: 10679
Name of Operator: LOGOS OPERATING LLC
Address: 2010 AFTON PLACE
City: FARMINGTON State: NM Zip: 87415

Status Summary:
 THIS IS A FOLLOW UP INSPECTION
 FOLLOW UP INSPECTION REQUIRED
 NO FOLLOW UP INSPECTION REQUIRED

Findings:
21 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Labowskie, Steve		steve.labowskie@state.co.us	COGCC
Sessions, Tamara	505-324-4145	tsessions@logosresourcesllc.com	SW Inspection Reports
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	SW Inspection Reports.

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
256122	WELL	PR	03/04/2000	GW	067-08272	IGNACIO 33-8 5A	PR

General Comment:
[Site inspection and equipment inventory with photos at the end of this report.](#)

Location

Lease Road:			
	Type	Access	
	comment:	Gravel access road.	
Corrective Action	L		Date:

Overall Good:

Signs/Marker:			
	Type	TANK LABELS/PLACARDS	
	Comment:	Labels and placards posted on sign on PBV catwalk.	
Corrective Action:			Date:
	Type	WELLHEAD	
	Comment:	Sign posted at entrance to location.	
Corrective Action:			Date:

Emergency Contact Number:

Comment:	Contact information posted on signs.				
Corrective Action:					Date: _____

Overall Good:

Spills:					
Type	Area	Volume			

In Containment: No

Comment:

Multiple Spills and Releases?

Equipment:					corrective date
Type:	Ancillary equipment	# 1			
	Comment:		Wellhead with dual block valve assembly producing out of (2) different formations (MV, DK).		
Corrective Action:				Date:	
Type:	Bradenhead	# 1			
	Comment:		Plumbed to surface		
Corrective Action:				Date:	
Type:	Flow Line	# 8			
	Comment:		2-2" steel flowlines from wellhead to separators. 2-1" steel flowlines from separator dump valves to produced water tank. 2-2" steel flowlines from separator becoming 2-4" flowlines to sales line valve riser on location. All points co-located and are in use.		
Corrective Action:				Date:	
Type:	Ancillary equipment	# 1			
	Comment:		Telemetry equipment installed on separator.		
Corrective Action:				Date:	
Type:	Gas Meter Run	# 2			
	Comment:		Dual gas meters on location producing from separate formations (MV, DK)		
Corrective Action:				Date:	

Type: Bird Protectors	# 2		
Comment:	On both separator stacks.		
Corrective Action:			Date:
Type: Horizontal Heated Separator	# 2		
Comment:	Separators producing from (2) different formations (MV, DK)		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Rectifier located on edge of location.		
Corrective Action:			Date:
Type: Ancillary equipment	# 1		
Comment:	Repeater tower on East side of location.		
Corrective Action:			Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	100 BBLs	PBV STEEL		
Comment:	125 BBL tank with expanded metal screen.				
Corrective Action:					Date:

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Compacted gravel berm around PBV.			
Corrective Action:				Date:

Venting:

Yes/No	NO	
Comment:		
Corrective Action:		Date:

Flaring:

Type	
Comment:	
Corrective Action:	Date:

Inspected Facilities

Facility ID: 256122 Type: WELL API Number: 067-08272 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing out of \(2\) different formations \(MV, DK\)](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Berms	Pass	Compaction	Pass			
Compaction	Pass	Gravel	Pass			
Gravel	Pass					

Comment: Stormwater berm along southern and western edge of location. Stormwater BMP's appear to be functioning at time of inspection.

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905944	Overview photo looking North.	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5018333