

**FORM  
INSP**Rev  
X/15

# State of Colorado

## Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/19/2019

Submitted Date:

12/19/2019

Document Number:

687905947

**FIELD INSPECTION FORM**
 Loc ID 326558 Inspector Name: Stewart, Joseph On-Site Inspection ☐ 2A Doc Num:
**Operator Information:**

OGCC Operator Number: 10679

Name of Operator: LOGOS OPERATING LLC

Address: 2010 AFTON PLACE

City: FARMINGTON State: NM Zip: 87415

**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**

17 Number of Comments

0 Number of Corrective Actions

☐ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE**
**Contact Information:**

Contact Name	Phone	Email	Comment
Rowley, Darren	505-947-4974	drowley@logosresourcesllc.com	<a href="#">SW Inspection Reports.</a>
Sessions, Tamara	505-324-4145	tsessions@logosresourcesllc.com	<a href="#">SW Inspection Reports</a>
Labowskie, Steve		steve.labowskie@state.co.us	<a href="#">COGCC</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
257222	WELL	PR	07/01/2019	GW	067-08297	IGNACIO 33-8 13R	PR

**General Comment:**
[Site inspection and equipment inventory with photos at the end of this report.](#)

Location				
<b>Lease Road:</b>				
Type	Access			
comment:	Gravel access road.			
Corrective Action	L			Date:
Overall Good: <input type="checkbox"/>				
<b>Signs/Marker:</b>				
Type	TANK LABELS/PLACARDS			
Comment:	Labels and placards posted on sign at tank			
Corrective Action:				Date:
Type	WELLHEAD			
Comment:	Sign posted at entrance to location.			
Corrective Action:				Date:
Emergency Contact Number:				
Comment:	Contact information posted on signs.			
Corrective Action:				Date: _____
Overall Good: <input type="checkbox"/>				
<b>Spills:</b>				
Type	Area	Volume		
In Containment: No				
Comment:				
<input type="checkbox"/> Multiple Spills and Releases?				
<b>Fencing/:</b>				
Type	TANK BATTERY			
Comment:	T-post and hogwire around PBV.			
Corrective Action:				Date:
<b>Equipment:</b>				
				corrective date
Type: Deadman # & Marked	# 4			
Comment:				
Corrective Action:				Date:
Type: Bird Protectors	# 1			
Comment:	On separator stack.			
Corrective Action:				Date:
Type: Flow Line	# 4			
Comment:	1-2" steel flowline from wellhead to separator. 1-2" steel flowline from separator blowdown to produced water tank. 1-1" steel flowline from separator dump valve to produced water tank. 1-2" steel flowline from separator to sales line. 1-2" unused steel flowline from wellhead to valve riser and LOTO. All points co-located.			
Corrective Action:				Date:
Type: Horizontal Heated Separator	# 1			
Comment:				

Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Wellhead with with dual block valve assembly installed on both producing formations, (MV, DK)		
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:	On separator skid.		
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:	Plumbed to surface.		
Corrective Action:		Date:	

**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	100 BBLs	PBV STEEL		,	
Comment:	125 BBL PBV with expanded metal screen on top.					
Corrective Action:					Date:	

**Paint**

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate
Comment:	Compacted gravel berm around PBV.			
Corrective Action:			Date:	

**Venting:**

Yes/No	NO	
Comment:		
Corrective Action:		Date:

**Flaring:**

Type	
Comment:	
Corrective Action:	Date:

<b>Inspected Facilities</b>				
Facility ID: 257222	Type: WELL	API Number: 067-08297	Status: PR	Insp. Status: PR
<b>Producing Well</b>				
Comment:	Producing.			
Corrective Action:				Date:

**Reclamation - Storm Water - Pit****Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass			
Compaction	Pass	Compaction	Pass			

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
687905948	Overview photo looking East.	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5018335">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5018335</a>