

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2019

Submitted Date:

12/19/2019

Document Number:

699800239**FIELD INSPECTION FORM**Loc ID 312698 Inspector Name: De Paolo, Corey On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**7 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

| Contact Name    | Phone | Email                                     | Comment |
|-----------------|-------|---|---------|
| , Caerus        |       | COGCC.inspections@caerus<br>oilandgas.com |         |
| Kellerby, Shaun |       | shaun.kellerby@state.co.us                |         |

**Inspected Facilities:**

| Facility ID | Type | Status | Status Date | Well Class | API Num   | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|---------------|-------------|
| 273954      | WELL | PR     | 09/01/2017  | GW         | 077-08825 | HYRUP 12-17   | PR          |

**General Comment:**

COGCC Inspection Report Summary  
 On Thursday 12/19/19 at approximately 14:00 hours, I, Inspector Corey De Paolo,  
 conducted an on-site inspection at CAERUS PICEANCE LLC HYRUP-68S96W /12SWSW,  
 Location #312698 in Mesa County Colorado.  
 While there, I observed normal production operations.  
 This is a summary of inspection report.

### Location

|                    |        |       |  |
|--------------------|--------|-------|--|
| <b>Lease Road:</b> |        |       |  |
| Type               | Access |       |  |
| comment:           |        |       |  |
| Corrective Action  | L      | Date: |  |

Overall Good: ☒

|                      |                      |       |  |
|----------------------|----------------------|-------|--|
| <b>Signs/Marker:</b> |                      |       |  |
| Type                 | TANK LABELS/PLACARDS |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | WELLHEAD             |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |
| Type                 | BATTERY              |       |  |
| Comment:             |                      |       |  |
| Corrective Action:   |                      | Date: |  |

|                           |              |
|---------------------------|--------------|
| Emergency Contact Number: |              |
| Comment:                  | 866-580-9382 |
| Corrective Action:        |              |
|                           | Date: _____  |

|                           |        |       |  |
|---------------------------|--------|-------|--|
| <b>Good Housekeeping:</b> |        |       |  |
| Type                      | DEBRIS |       |  |
| Comment:                  |        |       |  |
| Corrective Action:        |        | Date: |  |

Overall Good: ☒

|                |      |        |  |
|----------------|------|--------|--|
| <b>Spills:</b> |      |        |  |
| Type           | Area | Volume |  |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

|                    |                 |       |  |
|--------------------|-----------------|-------|--|
| <b>Fencing/:</b>   |                 |       |  |
| Type               | SEPARATOR       |       |  |
| Comment:           | Pipe rail fence |       |  |
| Corrective Action: |                 | Date: |  |
| Type               | WELLHEAD        |       |  |
| Comment:           | Hog panels      |       |  |
| Corrective Action: |                 | Date: |  |
| Type               | TANK BATTERY    |       |  |
| Comment:           | Hog panels      |       |  |
| Corrective Action: |                 | Date: |  |

|                                   |     |  |  |                 |
|-----------------------------------|-----|--|--|-----------------|
| <b>Equipment:</b>                 |     |  |  | corrective date |
| Type: Plunger Lift                | # 1 |  |  |                 |
| Comment:                          |     |  |  |                 |
| Corrective Action:                |     |  |  | Date:           |
| Type: Bird Protectors             | # 1 |  |  |                 |
| Comment:                          |     |  |  |                 |
| Corrective Action:                |     |  |  | Date:           |
| Type: Horizontal Heated Separator | # 1 |  |  |                 |
| Comment:                          |     |  |  |                 |
| Corrective Action:                |     |  |  | Date:           |

**Tanks and Berms:**

|                    |                  |          |           |         |        |  |
|--------------------|------------------|----------|-----------|---------|--------|--|
| Contents           | #                | Capacity | Type      | Tank ID | SE GPS |  |
| CONDENSATE         | 1                | OTHER    | STEEL AST |         | ,      |  |
| Comment:           | 210 bbl capacity |          |           |         |        |  |
| Corrective Action: |                  |          |           |         | Date:  |  |

**Paint**

|                  |          |  |  |  |  |
|------------------|----------|--|--|--|--|
| Condition        | Adequate |  |  |  |  |
| Other (Content)  |          |  |  |  |  |
| Other (Capacity) |          |  |  |  |  |
| Other (Type)     |          |  |  |  |  |

**Berms**

|                    |          |                     |                     |             |       |
|--------------------|----------|---------------------|---------------------|-------------|-------|
| Type               | Capacity | Permeability (Wall) | Permeability (Base) | Maintenance |       |
| Metal              | Adequate | Walls Sufficient    | Base Sufficient     | Adequate    |       |
| Comment:           |          |                     |                     |             |       |
| Corrective Action: |          |                     |                     |             | Date: |

**Venting:**

|                    |    |  |       |
|--------------------|----|--|-------|
| Yes/No             | NO |  |       |
| Comment:           |    |  |       |
| Corrective Action: |    |  | Date: |

**Flaring:**

|                    |  |       |
|--------------------|--|-------|
| Type               |  |       |
| Comment:           |  |       |
| Corrective Action: |  | Date: |

| Inspected Facilities |           |       |      |             |           |         |    |               |    |
|----------------------|-----------|-------|------|-------------|-----------|---------|----|---------------|----|
| Facility ID:         | 273954    | Type: | WELL | API Number: | 077-08825 | Status: | PR | Insp. Status: | PR |
| Producing Well       |           |       |      |             |           |         |    |               |    |
| Comment:             | Producing |       |      |             |           |         |    |               |    |
| Corrective Action:   |           |       |      | Date:       |           |         |    |               |    |

**Reclamation - Storm Water - Pit****Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Ditches          |                 |                         |                       |               |                          |         |
|                  |                 | Compaction              |                       |               |                          |         |
| Gravel           |                 |                         |                       |               |                          |         |
|                  |                 | Culverts                |                       |               |                          |         |
|                  |                 | Gravel                  |                       |               |                          |         |
| Compaction       |                 |                         |                       |               |                          |         |
|                  |                 | Ditches                 |                       |               |                          |         |
| Berms            |                 |                         |                       |               |                          |         |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description                 | URL   |
|--------------|-----------------------------|---|
| 699800240    | Photos for Insp. #699800239 | <a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5018346">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5018346</a> |