

**TEP Rocky  
Mountain LLC  
DOE 2-W-27  
Location # 335233**



TEP Rocky  
Mountain LLC  
DOE 2-W-27  
Location # 335233



TEP Rocky  
Mountain LLC  
DOE 2-W-27  
Location # 335233



4 - batteries not properly stored sitting at injection well.



4 - batteries not properly stored sitting at injection well.

TEP Rocky  
Mountain LLC  
DOE 2-W-27  
Location # 335233



Gates on well head fencing are leaning



Gates on well head fencing are leaning