

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/11/2019

Submitted Date:

12/16/2019

Document Number:

697600672

FIELD INSPECTION FORM

Loc ID 317729 Inspector Name: GINTAUTAS, PETER On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 46290
Name of Operator: KP KAUFFMAN COMPANY INC
Address: 1675 BROADWAY, STE 2800
City: DENVER State: CO Zip: 80202

Findings:

- 6 Number of Comments
- 2 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	303-825-4822	cogcc@kpk.com	Eng'g Project Mgr

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
239878	WELL	PR	04/12/1973	GW	123-07666	JOHN A KUNZMAN 1	EI

General Comment:

[production facilities not co-located with well](#)
[well only inspected in this report](#)

Location			
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	WELLHEAD		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:	on wellhead sign		Date: _____
Corrective Action:			
Good Housekeeping:			
Type	WEEDS		
Comment:	weeds at wellhead and surrounding area		
Corrective Action:	Comply with Rule 603.f .		Date: <u>12/23/2019</u>
Type	UNUSED EQUIPMENT		
Comment:	pumpjack at well is disassembled and laying on ground along with pumpjack fence alternate means of production at wellhead		
Corrective Action:	Comply with Rule 603.f .		Date: <u>01/16/2020</u>
Overall Good: <input type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:	no spills observed at surface near wellhead but snow cover in area		
<input type="checkbox"/> Multiple Spills and Releases?			
Equipment:			
Type: Pump Jack			# 1
Comment:			see comments above regarding unused equipment no production reported from well since May2019
Corrective Action:		Date:	
Type: Plunger Lift			# 1
Comment:			
Corrective Action:		Date:	
Venting:			
Yes/No			
Comment:			
Corrective Action:			Date:
Flaring:			
Type			
Comment:			
Corrective Action:			Date:

Inspected FacilitiesFacility ID: 239878 Type: WELL API Number: 123-07666 Status: PR Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402263627	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5013791
697600673	disassembled pumpjack at Kunzman A1 wellhead	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5013789
697600674	weeds and unused equipment	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5013790