

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-07674
Date: 12-20-2019



Photo 1. View of the project area from the northwestern corner facing center.



Photo 2. View of the southern project area from the southwestern corner facing eastward. Little desirable vegetation is present here. It appears that vegetation may have been killed. Area is approximately 75 feet wide and long.



Photo 3. View of stormwater flowing downslope away from the well pad toward a drainage. No stormwater controls are in place.



Photo 4. View of Russian thistles approximately 2-3 feet tall, within the northern project area.



Photo 5. View of reference area vegetation comprised of sagebrush shrubland and pinyon juniper/gambel oak woodland mosaic.