

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/19/2019

Submitted Date:

12/23/2019

Document Number:

688306585

FIELD INSPECTION FORM

Loc ID 317117 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 14855
Name of Operator: CENTRAL OPERATING INC
Address: 1600 BROADWAY STE 1050
City: DENVER State: CO Zip: 80202

Findings:

- 3 Number of Comments
- 1 Number of Corrective Actions
- Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Potter, Gail		centraloperatinginc@gmail.com	Office manager
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	
Whittington, Ellice		ellice.whittington@state.co.us	
MacLaren, Joe		joe.maclaren@state.co.us	
Staley, Conner	3038949576	coidenverproduction@gmail.com	
Quintana, Laney	(303) 894-9576	centraloperatinginc@gmail.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
236498	WELL	PR	07/03/1975	OW	121-08988	STATE 3	EG

General Comment:

COGCC Flowline Inspection/Reinspection. Photos Uploaded.

The Corrective Action identified during this COGCC (EG) field Inspection are located in the flowline section of report. ALL CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE.

Corrective actions from previous inspection were completed (stuffing box leak and fix access road).

Inspected Facilities

Facility ID: 236498 Type: WELL API Number: 121-08988 Status: PR Insp. Status: EG

Flowline

#1	Type:	of Lines
----	-------	----------

Flowline Description

Flowline Type: _____ Size: _____ Material: _____
 Variance: _____ Age: _____ Contents: _____

Integrity Summary

Failures: _____ Spills: _____ Repairs Made: _____
 Coatings: _____ H2S: _____ Cathodic Protection: _____

Pressure Testing

Witnessed: _____ Test Result: _____ Charted: _____

COGCC Rules(check all that apply)

1101. Installation and Reclamation 1102. Operations, Maintenance, and Repair 1103. Abandonment

Comment: This well is currently producing. The off location flowline (wellhead line) runs approximately 1880' north from the wellhead to the facility/battery. This off location flowline has not been registered with COGCC as operator has not submitted COGCC Form 44.
 Note: Operator has not registered any off location flowlines with COGCC. The Corrective Action outlined is applicable to all wells operated by Central Operating (including for this facility and the Marick, 121-08619). Additional inspections may be forthcoming.

Corrective Action: Operator shall comply with the following COGCC Rule: 1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off-location flowline in existence prior to May 1, 2018, must be registered by October 31,2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.

Date: 10/31/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688306596	Central Operating INC, State 3	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020985