

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2019

Submitted Date:

12/23/2019

Document Number:

688306561**FIELD INSPECTION FORM**Loc ID 320789 Inspector Name: Sherman, Susan On-Site Inspection ☐ 2A Doc Num: **Operator Information:**OGCC Operator Number: 10646Name of Operator: AXIS EXPLORATION LLCAddress: 370 17TH ST SUITE 5300City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**3 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Antonioli, Philip	720-345-4603	PAntonioli@extractionog.com	
Oil, Extraction	720-370-5540	COGCCInspections@extracti onog.com	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204932	WELL	SI	01/01/2018	GW	005-07017	HSR-HILL 10-21	PA

**General Comment:**[PA Inspection](#)

**Inspected Facilities**Facility ID: 204932 Type: WELL API Number: 005-07017 Status: SI Insp. Status: PA**Cement**Cement ContractorContractor Name: SPN

Contractor Phone: \_\_\_\_\_

Surface Casing

Cement Volume (sx): \_\_\_\_\_

Circulate to Surface: \_\_\_\_\_

Cement Fall Back: \_\_\_\_\_

Top Job, 1" Volume: \_\_\_\_\_

Intermediate Casing

Cement Volume (sxs): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Production Casing

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Plugging Operations

Depth Plugs(feet range): \_\_\_\_\_

Cement Volume (sx): \_\_\_\_\_

Good Return During Job: \_\_\_\_\_

Cement Type: \_\_\_\_\_

Comment:

12/18/2019

Enclosed combustor on well location and flaring. On 12/16/2019 the well had 1000 psi and on 12/18/2019 it had 200 psi, 30 psi on tubing.

12/20/2019

Not combusting.

Set 7725' CIBP on tubing with 5 sxs (Class G) set on top, Axis was going to pump 25 sxs from 7140'-6700' that afternoon and then shut down for holidays. Thermaltropic cement-15.8 ppg, 1.52 yield to be used. Kinetic truck brought water for cement from Eaton. Surefire wireline to perf @ 3500' after break. A current Form 17 was submitted but not uploaded per operator.

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Workover**Comment:

SPN Rig 718

Corrective Action: \_\_\_\_\_

Date: \_\_\_\_\_

**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688306610	Axis Exploration HSR-Hill 10-21 rig sign Brick Center	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020974">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020974</a>
688306611	Axis Exploration HSR-Hill 10-21 rig	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020975">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020975</a>
688306612	Axis Exploration HSR-Hill 10-21 SPN cementing	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020976">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020976</a>
688306613	xis Exploration HSR-Hill 10-21 tank waddles	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020977">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5020977</a>