

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/10/2019

Submitted Date:

12/17/2019

Document Number:

692401692**FIELD INSPECTION FORM**Loc ID 336021 Inspector Name: Colby, Lou On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 10447Name of Operator: URSA OPERATING COMPANY LLCAddress: 950 17TH STREET, SUITE 1900City: DENVER State: CO Zip: 80202**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**5 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Knudson, Dwayne	970-456-3335	dknudson@ursaresources.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
278645	WELL	PR	05/15/2006	GW	045-10901	SNYDER C1	RI
286234	WELL	PR	09/01/2019	GW	045-12628	SNYDER C8	RI
292155	WELL	PR	09/01/2019	GW	045-14606	SNYDER C9	RI

General Comment:

This is an Interim Reclamation & Stormwater focused Inspection. Any Corrective Actions from previous Inspections that have not been addressed are still applicable.

LocationOverall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Equipment:**

corrective date

Type: Other

#

Comment:

Wildlife Escape Board in cellar of Well#045-10901 is improperly adjusted; not in position to allow means of Wildlife egress. Base of board is wedged on cellar ring, not resting at cellar bottom.

Corrective Action:

Adjust Wildlife Escape Board in cellar of Well #045-10901 to maximize wildlife welfare; allowing means of Wildlife egress.

Date: 12/30/2019**Venting:**

Yes/No

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities									
Facility ID:	<u>278645</u>	Type:	<u>WELL</u>	API Number:	<u>045-10901</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>286234</u>	Type:	<u>WELL</u>	API Number:	<u>045-12628</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>
Facility ID:	<u>292155</u>	Type:	<u>WELL</u>	API Number:	<u>045-14606</u>	Status:	<u>PR</u>	Insp. Status:	<u>RI</u>

Reclamation - Storm Water - Pit**Interim Reclamation:**

Date Interim Reclamation Started: _____ Date Interim Reclamation Completed: _____

Land Use: _____

Comment: _____

1002 SITE PREPARATION AND STABILIZATION

1002a. FENCING _____

Comment _____

Corrective Action _____

Date _____

1002b. SOIL REMOVAL AND
SEGREGATION _____

Comment _____

Corrective Action _____

Date _____

1002c. PROTECTION OF SOILS _____

Comment _____

Corrective Action _____

Date _____

1002E. SURFACE DISTURBANCE MINIMIZATION _____

Comment _____

Corrective Action _____

Date _____

1003a. Waste and Debris removed? Pass

Comment _____

Corrective Action _____

Date _____

Unused or unneeded equipment onsite? Pass

Comment _____

Corrective Action _____

Date _____

Pit, cellars, rat holes and other bores closed? Pass

Comment _____

Corrective Action _____

Date _____

Guy line anchors marked? Pass

Comment _____

Corrective Action _____

Date _____

1003b. Area no longer in use? In Production areas stabilized ? Pass1003c. Compacted areas have been cross ripped? 1003d. Drilling pit closed? Pass Subsidence over on drill pit? PassCuttings management: 1003e. Areas no longer needed for drilling or subsequent operations for have been re-vegetated to 80% of pre-existing? FailProduction areas have been stabilized? PassSegregated soils have been replaced? **RESTORATION AND REVEGETATION**CroplandTop soil replaced Recontoured Perennial forage re-established Non-CroplandTop soil replaced Recontoured 80% Revegetation Fail

1003e. INTERIM VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER 1003 f. Weeds Noxious weeds? P

Comment

Vegetation in portions of the Interim Rec areas to North & West of Well pad is composed of Kochia; soils appear compacted, poor & gravelly. Topsoil may not have been replaced in these failed areas; as surrounding river bottom hay fields appear productive. It is recommended that Operator conduct Vegetation and Soils assessment.

Corrective Action

Reinstall Interim reclamation in Failed areas; conducting any activities necessary as indicated by Operator assessment, (ie: de-compacting, amending, re-seeding/inter-seeding or other). Reclamation activities to be complete by 6/1/20.

Date 06/01/2020Overall Interim Reclamation In Process**Final Reclamation/ Abandoned Location:**Date Final Reclamation Started: Date Final Reclamation Completed: Final Land Use: Reminder: Comment: Well plugged Pit mouse/rat holes, cellars backfilled Debris removed No disturbance /Location never built Access Roads Regraded Contoured Culverts removed Gravel removed Location and associated production facilities reclaimed Locations, facilities, roads, recontoured Compaction alleviation Dust and erosion control Non cropland: Revegetated 80% Cropland: perennial forage Weeds present Subsidence

1004.d. FINAL VEGETATION TRANSECT

TRANSECT RESULTS OF DISTURBED AREA% TRANSECT RESULTS OF REFERENCE AREA% TOTAL % OF DESIRABLE VEGETATION COVER VEGETATIVE COVER Comment:

Inspector Name: Colby, Lou

Corrective Action: <input style="width: 600px;" type="text"/>					Date <input style="width: 100px;" type="text"/>	
Overall Final Reclamation <input style="width: 150px;" type="text"/>		Well Release on Active Location <input style="width: 50px;" type="checkbox"/>		Multi-Well Location <input style="width: 50px;" type="checkbox"/>		
Storm Water:						
Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
<input style="width: 100px;" type="text"/>	<input style="width: 100px;" type="text"/>	<input style="width: 100px;" type="text"/>	<input style="width: 100px;" type="text"/>	<input style="width: 100px;" type="text"/>	<input style="width: 100px;" type="text"/>	<input style="width: 100px;" type="text"/>
Comment: <input style="width: 600px;" type="text" value="Site appears stable and has no Sediment Migration concerns at time of inspection."/>						
Corrective Action: <input style="width: 600px;" type="text"/>					Date: <input style="width: 100px;" type="text"/>	
Pits: <input checked="" type="checkbox"/> NO SURFACE INDICATION OF PIT						

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402265530	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015349
692401714	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015331