

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/17/2019

Submitted Date:

12/17/2019

Document Number:

699300758**FIELD INSPECTION FORM**Loc ID 322551 Inspector Name: Revas, Robbie On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☒ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		dnr_cogccengineering@state.co.us	
Pesika, Conor		conor.pesicka@state.co.us	
,		COGCCinspections@anadarko.com	<a href="#">All Inspections</a>

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
243835	WELL	TA	10/01/2019	GW	123-11627	UPRR 38 PAN AM "T" TRUE 1	TA

**General Comment:**

**Location**Overall Good: ☒

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:	
Comment:	
Corrective Action:	Date: _____

Overall Good: ☒

<b>Spills:</b>					
Type	Area	Volume			

In Containment: No

Comment: \_\_\_\_\_

☐ Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	AG fence		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Bradenhead	# 1		
Comment:	exposed at surface		
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 243835 Type: WELL API Number: 123-11627 Status: TA Insp. Status: TA

**Idle Well**

Purpose: ☐ Shut In ☒ Temporarily Abandoned

Reminder: \_\_\_\_\_

**Comment:** Well report show it as TA. Flowline and Riser appear to have been disconnected and removed. It appears to have been shut in since June 2016.  
 Form 42 was submitted on 6/23/2017 Doc. # 401317065 Flowline Abandoned on 6/13/2017 per Rule 1105.  
 It appears that the most current MIT on record was submitted on 5/16/2016. Form 42 Doc. # 401042962 as required by Rule 326. MIT should be done ASAP.

**Corrective Action:** Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326.c and 208.

Date: 01/17/2020

**COGCC Comments**

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Tuesday 12/17/2019 at approximately 1125 hrs. I, Inspector Robbie Revas, Conducted an on-site inspection at a Kerr McGee location.</p> <p>UPRR 38 Pan AM "T" True #1 API #05-123-11627 in Weld County Colorado.</p> <p>While there, I observed TA wellsite. This is a follow up inspection per Doc. # 699300100</p> <p>During this inspection the following compliance issues appear to have been addressed:</p> <p>603.f Housekeeping: Weeds growing on location have been cut &amp; removed see photos 1, 2 &amp; 3.</p> <p>603.f Housekeeping: Unused equipment on location has been reassembled on WH see 2.</p> <p>603.f Housekeeping: Unused riser on location is now LOTO see photo 3</p> <p>During this inspection the following compliance issue was observed:</p> <p>Well report show it as TA. It appears to have been shut in since June 2016.</p> <p>Form 42 was submitted on 6/23/2017 Doc. # 401317065 Flowline Abandoned on 6/13/2017.</p> <p>It appears that the most current MIT on record was submitted on 5/6/2016 Form 42 Doc. # 401042962.</p> <p>Required by Rule 326.c and Rule 208</p> <p>Perform successful mechanical integrity test. If a successful MIT can not be performed within 30 day CA time the well must be plugged within 3 months per Rule 326 and 208. CA date 1/17/2019.</p> <p>Location is dry with some snow on the ground, weather is clear.</p> <p>A follow up on this site inspection needs to be conducted to ensure that all compliance issues are addressed to comply with COGCC rules.</p> <p>Continuing education COGCC Inspection Report Summary.</p> <p>This is a summary of inspection report.</p>	revasr	12/17/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402265998	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015855">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015855</a>
699300759	Location pics	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015842">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5015842</a>