

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/18/2019

Submitted Date:

12/19/2019

Document Number:

697600706**FIELD INSPECTION FORM**Loc ID 336098 Inspector Name: GINTAUTAS, PETER On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 46290Name of Operator: KP KAUFFMAN COMPANY INCAddress: 1675 BROADWAY, STE 2800City: DENVER State: CO Zip: 80202**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Lara-Mesa, Susana	(303) 825-4822	cogcc@kpk.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
242435	WELL	SI	03/01/2018	OW	123-10226	JOHNSON, ROLLAND A UNIT D 1	EI
469799	TANK BATTERY	AC	12/12/2019		-	Roland Johnson Unit D 1 battery	EI

General Comment:

[well and battery inspected in this report on loation shared with otehr operator.](#)
[Inspection of other operator's well and battery in doc 697600698](#)

LocationOverall Good: ☒**Signs/Marker:**

Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:Comment: [contact information on wellhead and battery signs](#)Corrective Action: Date: **Good Housekeeping:**

Type	WEEDS		
Comment:	weeds around pumpjack and manifold		
Corrective Action:	Comply with Rule 603.f .	Date:	12/27/2019

Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: [no spills seen at surface but some snow cover](#)☐ Multiple Spills and Releases?**Fencing/:**

Type	PUMP JACK		
Comment:			
Corrective Action:		Date:	

Equipment:

Type: Bird Protectors	# 1		corrective date
Comment:			
Corrective Action:		Date:	
Type: Pump Jack	# 1		
Comment:			
Corrective Action:		Date:	
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	0				,	
Comment: no produced water vessel identified with this operator visible on location						
Corrective Action:					Date:	

Paint

Condition		
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:

Contents	#	Capacity	Type	Tank ID	SE GPS	
CRUDE OIL	1	300 BBLs	STEEL AST		40.155814,-104.814786	
Comment:						
Corrective Action:					Date:	

Paint

Condition	Adequate	
Other (Content)		
Other (Capacity)		
Other (Type)		

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient		Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No			
Comment:			
Corrective Action:		Date:	

Flaring:

Type		
Comment:		
Corrective Action:		Date:

Inspected Facilities

Facility ID: 242435 Type: WELL API Number: 123-10226 Status: SI Insp. Status: EI

Idle Well

Purpose: ☒ Shut In ☐ Temporarily Abandoned

Reminder: _____

Comment: last production reported in January 2018

Corrective Action: _____

Date: _____

Facility ID: 469799 Type: TANK API Number: - Status: AC Insp. Status: EI

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402267747	INSPECTION SUBMITTED	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017561
697600707	pump jack and wellhead sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017553
697600708	weeds at pumjack	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017554
697600709	crude oil storage tank and battery sign	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017555
697600710	weeds near flowline manifold , unused secondary pump station	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017556
697600711	separator	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5017557