

Inspection Photos
Operator: Hilcorp Energy
Location/API #: 067-06464
Date: 12-20-2019



Photo 1. View of the project area from the southwestern corner facing center.



Photo 2. View of the southern fill slope from the southwestern corner facing eastward. Revegetation is progressing with grasses such as smooth brome, intermediate wheatgrass, and crested wheatgrass.



Photo 3. View of the western project area from the northwestern corner facing southward. Bare soils and little desirable vegetation present in this area. Revegetation is needed.



Photo 4. View of reference area vegetation comprised of pinyon, juniper, and oak woodland vegetation.