

Inspection Photos  
Operator: Hilcorp Energy  
Location/API #: 067-07545  
Date: 12-23-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the eastern project area from the northeastern corner facing southward. Revegetation is largely comprised of crested wheatgrass, western wheatgrass, and sand dropseed.





Photo 3. View of musk thistles within the northern project area.





Photo 4. View of reference area vegetation comprised of open grass field with scattered cottonwood and gambel oak trees.