

# Inspection Photos

Operator: Enduring Resources  
Location/API #: 067-06574  
Date: 12-23-2019



Photo 1. View of the project area from the northeastern corner facing center.



Photo 2. View of the western project area from the northwestern corner facing southward. Revegetation is largely in a dormant or snow covered condition at this time.



Photo 3. View of the northern project area from the northeastern corner facing westward.





Photo 4. View of reference area vegetation comprised of open grass field with both native and introduced grasses in dormant vegetative condition.