

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/19/2019

Submitted Date:

12/20/2019

Document Number:

693200482**FIELD INSPECTION FORM**Loc ID 316328 Inspector Name: Murray, Richard On-Site Inspection ☐ 2A Doc Num: \_\_\_\_\_**Operator Information:**OGCC Operator Number: 26155Name of Operator: EAGLE OPERATING INCAddress: 2501 6TH ST SE STE BCity: MINOT State: ND Zip: 58701**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**6 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Schlagenhauf, Mark		mark.schlagenhauf@state.co.us	Engineering Integrity Supervisor
Whittington, Ellice		ellice.whittington@state.co.us	
Jensen, Jody		jodyjensen0@gmail.com	Current
Cavanaugh, Tom	303-726-1511	Geocav@comcast.net	Current
Mau, Bob	701-837-4780	eagleop@yahoo.com	Current

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
265235	WELL	PR	06/01/2018	OW	103-10261	E-M EMERALD C-1HZ	PR

**General Comment:**

Engineering Integrity Inspection performed on December 20, 2019

**Inspected Facilities**

Facility ID: 265235 Type: WELL API Number: 103-10261 Status: PR Insp. Status: PR

**Flowline**

#1	Type: Dump Line	1 of Lines
----	-----------------	------------

Flowline Description

Flowline Type: Dump Line Size: 2" Material: Carbon Steel  
 Variance: Age: 5-10 Yrs Contents: Multiphase

Integrity Summary

Failures: Spills: Repairs Made:  
 Coatings: H2S: Cathodic Protection:

Pressure Testing

Witnessed: Test Result: Charted:

COGCC Rules(check all that apply)

☐ 1101. Installation and Reclamation ☒ 1102. Operations, Maintenance, and Repair ☐ 1103. Abandonment

Comment: The off location flowline (wellhead line) runs approximately 1888' NW from the wellhead to facility/ battery. Flowline services 1 wells in area. This off location flowline has not been registered with COGCC; Operator has not submitted COGCC Form 44. Note: Operator has not registered any off location flowlines with COGCC; Corrective Action outlined may be applicable to additional wells operated by Eagle Operating INC.

Corrective Action: Operator shall comply with the following COGCC rule: 1101.a. Off-Location Flowline Registration. (1) An operator must register an off-location flowline constructed on or after May 1, 2018, by submitting a Flowline Report, Form 44, to the Director within 30 days after the flowline is placed into service. An off-location flowline in existence prior to May 1, 2018, must be registered by October 31, 2019. An off-location flowline registered as part of a produced water transfer system is not subject to this requirement.

Date: 10/31/2019

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
402269483	INSPECTION SUBMITTED	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5019456">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5019456</a>
693200483	photo log	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5019455">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5019455</a>