

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/27/2019

Submitted Date:

12/27/2019

Document Number:

699100805**FIELD INSPECTION FORM**

Loc ID 329935 Inspector Name: Burns, Adam On-Site Inspection ☐ 2A Doc Num: _____

Operator Information:OGCC Operator Number: 100322Name of Operator: NOBLE ENERGY INCAddress: 1001 NOBLE ENERGY WAYCity: HOUSTON State: TX Zip: 77070**Status Summary:**☐ THIS IS A FOLLOW UP INSPECTION☒ FOLLOW UP INSPECTION REQUIRED☐ NO FOLLOW UP INSPECTION REQUIRED**Findings:**13 Number of Comments2 Number of Corrective Actions☒ Corrective Action Response Requested

**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**

Contact Information:

Contact Name	Phone	Email	Comment
,		NBL_DJBU_Inspections@NB LENERGY.COM	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
250255	WELL	PR	10/03/2007	OW	123-18058	UPV 25-214	PR

General Comment:

Location

Overall Good: ☒

Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:		Date:	
Type	CONTAINERS		
Comment:	Methonal system		
Corrective Action:		Date:	
Type	WELLHEAD		
Comment:			
Corrective Action:		Date:	
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:		Date:	

Emergency Contact Number:

Comment: Adequate

Corrective Action:

Date: _____

Good Housekeeping:

Type	TRASH		
Comment:	Trash on the south side of tank battery needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/08/2020
Type	TRASH		
Comment:	Trash around methanol system needs to be removed for good housekeeping. See attached photos.		
Corrective Action:	Comply with Rule 603.f .	Date:	01/08/2020

Overall Good: ☐

Spills:				
Type	Area	Volume		

In Containment: No

Comment:

☐ Multiple Spills and Releases?

Fencing/:			
Type	SEPARATOR		
Comment:	Barbwire		
Corrective Action:		Date:	
Type	IGNITOR/COMBUSTOR		
Comment:	X2 barbwire		
Corrective Action:		Date:	

Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	
Type	TANK BATTERY		
Comment:	Barbwire		
Corrective Action:		Date:	

Equipment:

			corrective date
Type: Horizontal Heated Separator	# 1		
Comment:			
Corrective Action:		Date:	
Type: Pig Station	# 1		
Comment:			
Corrective Action:		Date:	
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Ancillary equipment	# 1		
Comment:	Methanol System		
Corrective Action:		Date:	
Type: Bird Protectors	# 3		
Comment:			
Corrective Action:		Date:	
Type: Emission Control Device	# 2		
Comment:			
Corrective Action:		Date:	
Type: Gas Meter Run	# 1		
Comment:			
Corrective Action:		Date:	

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS	
PRODUCED WATER	1	OTHER	PBV CONCRETE		,	
Comment:	Shares containment with crude oil tank.					
Corrective Action:					Date:	

Paint

Condition			
Other (Content)			
Other (Capacity)	53 BBL		
Other (Type)			

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
------	----------	---------------------	---------------------	-------------

Comment:							
Corrective Action:							Date:
Contents	#	Capacity	Type	Tank ID	SE GPS		
CRUDE OIL	1	300 BBLs	STEEL AST		40.287720,-104.496330		
Comment:							
Corrective Action:							Date:

Paint

Condition	Adequate						
Other (Content)							
Other (Capacity)							
Other (Type)							

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance			
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate			
Comment:							
Corrective Action:							Date:

Venting:

Yes/No	NO						
Comment:							
Corrective Action:						Date:	

Flaring:

Type							
Comment:							
Corrective Action:						Date:	

Inspected Facilities

Facility ID: 250255 Type: WELL API Number: 123-18058 Status: PR Insp. Status: PR

Producing WellComment: PR

Corrective Action:

Date:

COGCC Comments

Comment	User	Date
<p>COGCC Inspection Report Summary</p> <p>On Friday 12/27/19 at approximately 0751 hrs, I, Inspector Adam Burns, Conducted an on-site inspection at UPV 25-214 of Noble Energy, at Location ID #329935 in Weld County, Colorado.</p> <p>During this inspection the following possible compliance issues were observed:</p> <p>Trash around methanol system needs to be removed for good housekeeping. Comply with Rule 603.f.</p> <p>With a corrective date of 1/8/20.</p> <p>Trash on the south side of tank battery needs to be removed for good housekeeping. Comply with Rule 603.f.</p> <p>With a corrective date of 1/8/20.</p> <p>See attached photos</p> <p>A follow up on this site inspection needs to be conducted to ensure the compliance issues have been corrected to comply with COGCC rules.</p> <p>This is a summary of inspection report.</p> <p>Continuing education inspections</p>	burnsa	12/27/2019

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699100806	Inspection Photos	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5022477