

# Inspection Photos

API: 05-025-06022

Operator: GRAND MESA OPERATING

Inspection Date: 12/18/2019



**COLORADO**

Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019

## Inspection Photos



**Photo 1.** Facing southwest along the two track road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 2.** There are signs stormwater has flowed at the low point of the road crossing, shown in area of red arrow.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 3.** The culvert further west along the road has washed out. Erosion has occurred around the culvert.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 4.** Facing west along the two track access road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 5.** Facing southeast along the two track road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 6.** There is an ephemeral stream crossing at this point along the two track road. This area appears to be stabilized.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 7.** Facing southeast along the two track road.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 8.** Facing southwest along the reclaimed portion of the road. It appears vehicles have been driving at this area. Vegetation does not appear to be establishing.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 9.** Facing southwest along the reclaimed portion of the road. It appears vehicles have been driving at this area. There are numerous Buffaloburs growing in the reclaimed area.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 10.** Facing south toward the location. There is a perimeter fence around the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 11.** Facing northeast at the center of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 12.** Facing northwest at the center of the location.




**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 13.** Facing southwest at the center of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 14.** Facing southeast at the center of the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 15.** View of groundcover. There is cracks along the ground.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 16.** There is some vegetation establishing in areas. Vegetation noticed was Sideoats grama, Blue grama, and Sand dropseed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 17.** There is numerous Buffalobur throughout the location, which is a native annual specie.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 18.** Facing southwest toward the location. There is predominately undesirable species growing at the location.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019



## Inspection Photos



**Photo 19.** Facing east toward the surrounding reference area which consists of predominately Blue grama and Sand dropseed.



**COLORADO**  
Oil & Gas Conservation  
Commission

Department of Natural Resources

API: 05-025-06022 | Date: 12/18/2019