

Construction and Stormwater Inspection

December 26, 2019

Operator: CONFLUENCE DJ LLC- #10518

Location ID: 453535

Inspection Document #: 697500950

Weld County, CO

SESE Section 31 T1N R65W

Chris Binschus
Reclamation Specialist, COGCC



COLORADO
Oil & Gas Conservation
Commission

Department of Natural Resources

Inspection Photos
Location Name: Missouri /31
Location ID: 453535



Photo 1. Photo taken from the entrance of the location on 12/9/2019, facing North. The current vehicle tracking device BMPs are not adequate to be in compliance with Rule 1002.f.(2)F.

Inspection Photos
Location Name: Missouri /31
Location ID: 453535



Photo 2. Photo taken from the entrance of the location on 12/26/2019, facing North. The current vehicle tracking device BMPs are not adequate to be in compliance with Rule 1002.f.(2)F.

Note: Operator has not installed any additional vehicle tracking device BMPs to access road since the previous inspection. As the previous inspection noted, the current vehicle tracking device BMPs were not adequate and remain inadequate.

Inspection Photos
Location Name: Missouri /31
Location ID: 453535



Photo 3. Photo taken from a portion of the vehicle tracking device BMP, facing North. The current vehicle tracking device BMPs are not adequate BMPs for this location.

Inspection Photos
Location Name: Missouri /31
Location ID: 453535



Photo 4. Close up photo taken from a portion of the rip-rap BMP that is not in proper functioning condition.

Inspection Photos
Location Name: Missouri /31
Location ID: 453535



Photo 5. Photo taken west of the entrance on CR 2, facing East. Photo illustrates material tracked onto the county road.

Inspection Photos
Location Name: Missouri /31
Location ID: 453535



Photo 6. Photo taken ~500 feet west of the entrance on CR 2, facing East. Photo illustrates material tracked onto the county road.