

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/27/2019

Submitted Date:

12/27/2019

Document Number:

688306620

FIELD INSPECTION FORM

Loc ID 320789 Inspector Name: Sherman, Susan On-Site Inspection 2A Doc Num: _____

Operator Information:

OGCC Operator Number: 10646
Name of Operator: AXIS EXPLORATION LLC
Address: 370 17TH ST SUITE 5300
City: DENVER State: CO Zip: 80202

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Findings:

3 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Antonioli, Philip	720-345-4603	PAntonioli@extractionog.com	
Oil, Extraction	720-370-5540	COGCCInspections@extracti onog.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
204932	WELL	SI	01/01/2018	GW	005-07017	HSR-HILL 10-21	PA

General Comment:

PA Inspection, PA completed

Inspected Facilities

Facility ID: 204932 Type: WELL API Number: 005-07017 Status: SI Insp. Status: PA

Cement

Cement Contractor

Contractor Name: SPN Contractor Phone: _____

Surface Casing

Cement Volume (sx): _____ Circulate to Surface: _____
 Cement Fall Back: _____ Top Job, 1" Volume: _____

Intermediate Casing

Cement Volume (sxs): _____ Good Return During Job: _____

Production Casing

Cement Volume (sx): _____ Good Return During Job: _____

Plugging Operations

Depth Plugs(feet range): _____ Cement Volume (sx): _____

Good Return During Job: _____ Cement Type: _____

Comment: 12/26/2019
 Surefire wireline and SPN for 3500' plug-DNW.
 12/27/2019
 SPN pumped 178 sxs from 1900 to surface as casing plug. Will tag with cut, cap and cover on 12/31/19 or 1/1/2020.

Corrective Action: _____ Date: _____

Workover

Comment: SPN Rig 718 PA, rigged down on 12/27/2019 and moved to next location, 005-06358.

Corrective Action: _____ Date: _____

Attached Documents

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
688306635	Axis HSR-Hill 10-21 PA	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5023409