

**FORM
INSP**Rev
X/15**State of Colorado
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/27/2019

Submitted Date:

12/27/2019

Document Number:

699500472**FIELD INSPECTION FORM**Loc ID 436477 Inspector Name: MEDINA, JUSTIN On-Site Inspection ☐ 2A Doc Num: _____**Operator Information:**OGCC Operator Number: 47120Name of Operator: KERR MCGEE OIL & GAS ONSHORE LPAddress: P O BOX 173779City: DENVER State: CO Zip: 80217-**Status Summary:**

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☒ NO FOLLOW UP INSPECTION REQUIRED

Findings:5 Number of Comments0 Number of Corrective Actions☐ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
,		COGCCinspections@anadarko.com	All Inspections

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
436474	WELL	SI	06/01/2019	OW	123-39155	NRC 28N-5HZ	SI
436475	WELL	SI	06/01/2019	OW	123-39156	NRC 27N-5HZ	SI
436476	WELL	SI	06/01/2019	OW	123-39157	NRC 26N-5HZ	SI
436595	WELL	SI	01/01/2018	OW	123-39190	NRC 2C-5HZ	SI
436598	WELL	SI	02/01/2018	OW	123-39192	NRC 1C-5HZ	SI

General Comment:

LocationOverall Good: ☒

Emergency Contact Number:

Comment:

Corrective Action:

Date: _____

Overall Good: ☒**Spills:**

Type

Area

Volume

In Containment: No

Comment:

☐ Multiple Spills and Releases?**Fencing/:**

Type WELLHEAD

Comment: Red AG fencing

Corrective Action:

Date:

Equipment:

corrective date

Type: Ancillary equipment

5

Comment: Automation

Corrective Action:

Date:

Type: Bradenhead

5

Comment:

Corrective Action:

Date:

Type: Plunger Lift

5

Comment:

Corrective Action:

Date:

Venting:

Yes/No NO

Comment:

Corrective Action:

Date:

Flaring:

Type

Comment:

Corrective Action:

Date:

Inspected Facilities

Facility ID: <u>436474</u>	Type: <u>WELL</u>	API Number: <u>123-39155</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>436475</u>	Type: <u>WELL</u>	API Number: <u>123-39156</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>436476</u>	Type: <u>WELL</u>	API Number: <u>123-39157</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>436595</u>	Type: <u>WELL</u>	API Number: <u>123-39190</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>
Facility ID: <u>436598</u>	Type: <u>WELL</u>	API Number: <u>123-39192</u>	Status: <u>SI</u>	Insp. Status: <u>SI</u>

Idle WellPurpose: ☒ Shut In ☐ Temporarily Abandoned Reminder: _____Comment: Corrective Action: Date: _____

Reclamation - Storm Water - Pit**Storm Water:**

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**COGCC Comments**

Comment	User	Date
At time of inspection location appears to be in compliance with COGCC rules. At time of inspection perception of location may have been distorted due to weather conditions.	medinaj	12/27/2019

Attached DocumentsYou can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
699500473	pics	http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5023779