

## Inspection Photos

Location Name: Clem Jr. 67S95W 15NWE (PB-15) Pad & PB15 Dumpline Failure

Location ID: #334653 & Spill/Release ID: #470298

Inspection Date: December 20, 2019



Photo #1 – View of separators on south side of pad.



Photo #2 – Subsidence area north of separators.



## Inspection Photos

Location Name: Clem Jr. 67S95W 15NWE (PB-15) Pad & PB15 Dumpline Failure

Location ID: #334653 & Spill/Release ID: #470298

Inspection Date: December 20, 2019



Photo #3 – ECD located west of separators.



Photo #4 – View of tank battery, from east.





## Inspection Photos

Location Name: Clem Jr. 67S95W 15NWE (PB-15) Pad & PB15 Dumpline Failure

Location ID: #334653 & Spill/Release ID: #470298

Inspection Date: December 20, 2019



**Photo #5 – Dump line located outside SE corner of tank battery.**



**Photo #6 – Tank battery secondary containment area contained ice and fluid on inspection date. No hydrocarbon sheens or odors were observed inside of secondary containment area on inspection date.**

**Ends of liner panels were observed sticking up from bottom of containment area on inspection date.**



**COLORADO**

**Oil & Gas Conservation  
Commission**

Department of Natural Resources



## Inspection Photos

Location Name: Clem Jr. 67S95W 15NWE (PB-15) Pad & PB15 Dumpline Failure

Location ID: #334653 & Spill/Release ID: #470298

Inspection Date: December 20, 2019



**Photo #7 – Pinhole observed in liner inside of tank battery secondary containment area.**



**Photo #8 – Ends of liner panels were observed sticking up from bottom of containment area on inspection date.**





## Inspection Photos

Location Name: Clem Jr. 67S95W 15NWN (PB-15) Pad & PB15 Dumpline Failure

Location ID: #334653 & Spill/Release ID: #470298

Inspection Date: December 20, 2019



Photo #9 – Sign for PB15 Clem Jr. 15-6 wellhead.



Photo #10 – Localized accumulation of oil-stained soil observed on north side of PB15 Clem Jr. 15-6 wellhead.



**COLORADO**  
Oil & Gas Conservation  
Commission  
Department of Natural Resources



## Inspection Photos

Location Name: Clem Jr. 67S95W 15NWE (PB-15) Pad & PB15 Dumpline Failure

Location ID: #334653 & Spill/Release ID: #470298

Inspection Date: December 20, 2019



Photo #11 - Sign for PB15 Clem Jr. 15-2BB wellhead.



Photo #12 - Localized accumulation of oil-stained soil observed on north side of PB15 Clem Jr. 15-2BB wellhead.