

**FORM
INSP**Rev
X/15

State of Colorado

Oil and Gas Conservation Commission

 1120 Lincoln Street, Suite 801, Denver, Colorado 80203
 Phone: (303) 894-2100 Fax: (303) 894-2109


Inspection Date:

12/30/2019

Submitted Date:

12/30/2019

Document Number:

697000334

FIELD INSPECTION FORM
 Loc ID 430382 Inspector Name: Welsh, Brian On-Site Inspection ☐ 2A Doc Num:
Operator Information:

OGCC Operator Number: 10460

Name of Operator: HIGH PLAINS ENERGY LLC

Address: 4545 S MONACO STREET #116

City: DENVER State: CO Zip: 80237

Status Summary:

- ☐ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

Findings:

12 Number of Comments

2 Number of Corrective Actions

☒ Corrective Action Response Requested
**ANY CORRECTIVE ACTION(S) FROM
PREVIOUS INSPECTIONS THAT HAVE NOT
BEEN ADDRESSED ARE STILL APPLICABLE**
Contact Information:

| Contact Name | Phone | Email | Comment |
|--------------|----------------|----------------------------------|---------|
| Wheat, Randy | (720) 480-7776 | rvwheat@comcast.net | |
| , | | dnr_cogccengineering@state.co.us | |

Inspected Facilities:

| Facility ID | Type | Status | Status Date | Well Class | API Num | Facility Name | Insp Status |
|-------------|------|--------|-------------|------------|-----------|------------------------------|-------------|
| 431414 | WELL | SI | 01/01/2015 | OW | 017-07727 | PRONGHORN STATE 16-15-48 1-H | TA |

General Comment:

Routine Inspection

Location

| | | | |
|--------------------|--|--|-------|
| Lease Road: | | | |
| Type | Access | | |
| comment: | Gravel road through pasture off of county road | | |
| Corrective Action | L | | Date: |

Overall Good: ☒

| | | | |
|----------------------|--------------------------------|--|-------|
| Signs/Marker: | | | |
| Type | WELLHEAD | | |
| Comment: | Lease sign by gate at entrance | | |
| Corrective Action: | | | Date: |

| | | |
|---------------------------|----------------------|----------------------------|
| Emergency Contact Number: | | |
| Comment: | <input type="text"/> | |
| Corrective Action: | <input type="text"/> | Date: <input type="text"/> |

| | | | |
|---------------------------|--|--|------------------|
| Good Housekeeping: | | | |
| Type | UNUSED EQUIPMENT | | |
| Comment: | Panels laying in berms. Random valves and piping laying around | | |
| Corrective Action: | Clean up pipe, fittings, valves, concrete posts from location | | Date: 03/30/2020 |

Overall Good: ☐

| | | | |
|----------------|------|--------|--|
| Spills: | | | |
| Type | Area | Volume | |

In Containment: No

Comment: ☐ Multiple Spills and Releases?

| | | | |
|--------------------|-----------------------------------|--|-------|
| Fencing/: | | | |
| Type | LOCATION | | |
| Comment: | Wire fence around entire location | | |
| Corrective Action: | | | Date: |

| | | | |
|-------------------------------|-----------------------|--|-----------------|
| Equipment: | | | corrective date |
| Type: Vertical Heater Treater | # 0 | | |
| Comment: | Removed from location | | |
| Corrective Action: | | | Date: |
| Type: Ancillary equipment | # 0 | | |
| Comment: | Removed from location | | |
| Corrective Action: | | | Date: |
| Type: Gas Meter Run | # 0 | | |
| Comment: | Removed from location | | |
| Corrective Action: | | | Date: |
| Type: Flare | # 0 | | |
| Comment: | Removed from location | | |

| | | | |
|--------------------------|-----------------------|-------|--|
| Corrective Action: | | Date: | |
| Type: Vertical Separator | # 0 | | |
| Comment: | Removed from location | | |
| Corrective Action: | | Date: | |
| Type: FWKO | # 0 | | |
| Comment: | Removed from location | | |
| Corrective Action: | | Date: | |

Venting:

| | | | |
|--------------------|--|-------|--|
| Yes/No | | | |
| Comment: | | | |
| Corrective Action: | | Date: | |

Flaring:

| | | |
|--------------------|--|-------|
| Type | | |
| Comment: | | |
| Corrective Action: | | Date: |

Inspected FacilitiesFacility ID: 431414 Type: WELL API Number: 017-07727 Status: SI Insp. Status: TA**Idle Well**Purpose: ☐ Shut In ☒ Temporarily Abandoned Reminder: _____Comment: Well is TA at time of inspection. Passing MIT performed on 7/3/14. Well is past due for MIT

Corrective Action: Contact COGCC Engineering within 10 days of receipt of this inspection for directives Date: 01/09/2020

Reclamation - Storm Water - Pit**Storm Water:**

| Loc Erosion BMPs | BMP Maintenance | Lease Road Erosion BMPs | Lease BMP Maintenance | Chemical BMPs | Chemical BMP Maintenance | Comment |
|------------------|-----------------|-------------------------|-----------------------|---------------|--------------------------|---------|
| Gravel | Pass | Gravel | Pass | | | |

Comment: Corrective Action: Date: **Pits:** ☒ NO SURFACE INDICATION OF PIT**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

| Document Num | Description | URL |
|--------------|-----------------|---|
| 697000340 | Location photos | http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5024939 |