

**FORM
INSP**

Rev
X/15

**State of Colorado
Oil and Gas Conservation Commission**

1120 Lincoln Street, Suite 801, Denver, Colorado 80203
Phone: (303) 894-2100 Fax: (303) 894-2109



Inspection Date:

12/26/2019

Submitted Date:

12/30/2019

Document Number:

697000318

FIELD INSPECTION FORM

Loc ID 321570 Inspector Name: Welsh, Brian On-Site Inspection 2A Doc Num: _____

Status Summary:

- THIS IS A FOLLOW UP INSPECTION
- FOLLOW UP INSPECTION REQUIRED
- NO FOLLOW UP INSPECTION REQUIRED

Operator Information:

OGCC Operator Number: 61250
Name of Operator: MULL DRILLING COMPANY INC
Address: 1700 N WATERFRONT PKWY B#1200
City: WICHITA State: KS Zip: 67206-

Findings:

21 Number of Comments
0 Number of Corrective Actions
 Corrective Action Response Requested

ANY CORRECTIVE ACTION(S) FROM PREVIOUS INSPECTIONS THAT HAVE NOT BEEN ADDRESSED ARE STILL APPLICABLE

Contact Information:

Contact Name	Phone	Email	Comment
Akers, Tracy	719-342-1813	takers@mulldrilling.com	

Inspected Facilities:

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
207322	WELL	PR	06/03/2002	OW	017-06257	MULL UNIT 11	PR

General Comment:

[Routine Inspection](#)

Location			
Lease Road:			
Type	Access		
comment:	Gravel road through pasture		
Corrective Action:			Date:
Overall Good: <input checked="" type="checkbox"/>			
Signs/Marker:			
Type	BATTERY		
Comment:			
Corrective Action:			Date:
Type	WELLHEAD		
Comment:	Lease sign by unit		
Corrective Action:			Date:
Type	CONTAINERS		
Comment:	Stickers on chemical drums		
Corrective Action:			Date:
Type	TANK LABELS/PLACARDS		
Comment:			
Corrective Action:			Date:
Emergency Contact Number:			
Comment:			
Corrective Action:			Date: _____
Overall Good: <input checked="" type="checkbox"/>			
Spills:			
Type	Area	Volume	
In Containment: No			
Comment:			
<input type="checkbox"/> Multiple Spills and Releases?			
Fencing/:			
Type	TANK BATTERY		
Comment:	Tank battery is 3/4 fenced with wire		
Corrective Action:			Date:
Type	PUMP JACK		
Comment:	Metal panels around unit, wellhead and metal shed		
Corrective Action:			Date:
Equipment:			
Type: Compressor	# 1		corrective date
Comment:	Gas vent recovery compressor for flare on south side of location		
Corrective Action:			Date:

Type: Vertical Heater Treater	# 2	
Comment:	2-Treaters with metal sheds	
Corrective Action:		Date:
Type: LACT	# 1	
Comment:	LACT unit and electric panels on east side of tank battery	
Corrective Action:		Date:
Type: Vertical Separator	# 2	
Comment:	2-Vertical gas separators in metal manifold shed	
Corrective Action:		Date:
Type: Flare	# 1	
Comment:	Flare is at the southeast corner of location	
Corrective Action:		Date:
Type: Pump Jack	# 1	
Comment:	Lufkin 456	
Corrective Action:		Date:
Type: Ancillary equipment	# 9	
Comment:	Electric panel, cathodic rectifier, chemical drums w/containment, blowdown tank w/containment, telemetry equipment at LACT unit, propane tank by flare, blowdown tank, electric transfer pump in metal shed at water/oil tanks	
Corrective Action:		Date:
Type: Compressor	# 1	
Comment:	Electric skid mounted dual booster compressor in metal shed	
Corrective Action:		Date:
Type: Prime Mover	# 1	
Comment:	Electric motor	
Corrective Action:		Date:

Tanks and Berms:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	OTHER	FIBERGLASS AST		38.861020,-102.903410
Comment:	Transfer tank on north side of production tanks				
Corrective Action:					Date:

Paint

Condition	
Other (Content)	
Other (Capacity)	175bbbls
Other (Type)	

Berms

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Comment:				
Corrective Action:				Date:

Contents	#	Capacity	Type	Tank ID	SE GPS
PRODUCED WATER	1	300 BBLs	FIBERGLASS AST		38.861020,-102.903410
Comment: Transfer tank on north side of production tanks					
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	1	OTHER	STEEL AST		38.861020,-102.903210
Comment: Vent tank on east side water tanks					
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)	250bbbs				
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	
Earth	Adequate	Walls Sufficient	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:
Contents	#	Capacity	Type	Tank ID	SE GPS
CRUDE OIL	4	400 BBLs	STEEL AST		38.860660,-102.903400
Comment: MUSF #2 Tank battery for (Mull Unit 8, 9, 10, 11, 12, 13, 22) 1-Steel tank not insulated (NW tank) 3-Insulated tanks					
Corrective Action:					Date:
<u>Paint</u>					
Condition					
Other (Content)					
Other (Capacity)					
Other (Type)					
<u>Berms</u>					
Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance	

Earth	Adequate	Walls Sufficent	Base Sufficient	Adequate	
Comment:					
Corrective Action:					Date:

Venting:

Yes/No	NO		
Comment:			
Corrective Action:			Date:

Flaring:

Type	Ignitor/Combustor	
Comment:	Not lit at time of inspection	
Corrective Action:		Date:

Inspected Facilities

Facility ID: 207322 Type: WELL API Number: 017-06257 Status: PR Insp. Status: PR

Producing Well

Comment: [Producing. Central tank battery for \(Mull Unit 8, 9, 10, 11, 12, 13, 14, 22\) @ MUSF #2 TB 1750' W @ 38.860660/-102.903400](#)

Corrective Action:

Date:

Reclamation - Storm Water - Pit

Storm Water:

Loc Erosion BMPs	BMP Maintenance	Lease Road Erosion BMPs	Lease BMP Maintenance	Chemical BMPs	Chemical BMP Maintenance	Comment
Gravel	Pass	Gravel	Pass	Material Handling And Spill Prevention	Pass	

Comment:

Corrective Action:

Date: _____

Pits: NO SURFACE INDICATION OF PIT