

Inspection Photos

Location Name: N Parachute WF15A-23 F23596 Pad

Location ID: #335667 & Spill/Release ID: #470366

Inspection Date: December 20, 2019



Photo #1 – Sign at entrance to pad.



Photo #2 – View of tank battery from northeast.



Inspection Photos

Location Name: N Parachute WF15A-23 F23596 Pad

Location ID: #335667 & Spill/Release ID: #470366

Inspection Date: December 20, 2019



Photo #3 – View of equipment on west side of tank battery.



Photo #4 – West side of tank battery berm was covered on inspection date.



COLORADO
Oil & Gas Conservation
Commission
Department of Natural Resources

Inspection Photos

Location Name: N Parachute WF15A-23 F23596 Pad

Location ID: #335667 & Spill/Release ID: #470366

Inspection Date: December 20, 2019



Photo #5 – Tank battery loadout.



Photo #6 – Damaged section of tank battery liner, near tank battery loadout (1).



Inspection Photos

Location Name: N Parachute WF15A-23 F23596 Pad

Location ID: #335667 & Spill/Release ID: #470366

Inspection Date: December 20, 2019



Photo #7 - Damaged section of tank battery liner, near tank battery loadout (2).



Photo #8 – Ice and snow inside of tank battery containment area.



Inspection Photos

Location Name: N Parachute WF15A-23 F23596 Pad

Location ID: #335667 & Spill/Release ID: #470366

Inspection Date: December 20, 2019



Photo #9 – Day tank inside of secondary containment.



Photo #10 – View of repaired dumphine inside of excavation.

