

**FORM  
INSP**Rev  
X/15**State of Colorado  
Oil and Gas Conservation Commission**1120 Lincoln Street, Suite 801, Denver, Colorado 80203  
Phone: (303) 894-2100 Fax: (303) 894-2109

Inspection Date:

12/20/2019

Submitted Date:

12/31/2019

Document Number:

698100112**FIELD INSPECTION FORM**Loc ID 335667 Inspector Name: Arauza, Steven On-Site Inspection ☐ 2A Doc Num: ☐**Operator Information:**OGCC Operator Number: 10456Name of Operator: CAERUS PICEANCE LLCAddress: 1001 17TH STREET #1600City: DENVER State: CO Zip: 80202**Status Summary:**

- ☒ THIS IS A FOLLOW UP INSPECTION
- ☐ FOLLOW UP INSPECTION REQUIRED
- ☐ NO FOLLOW UP INSPECTION REQUIRED

**Findings:**4 Number of Comments1 Number of Corrective Actions☒ Corrective Action Response Requested**ANY CORRECTIVE ACTION(S) FROM  
PREVIOUS INSPECTIONS THAT HAVE NOT  
BEEN ADDRESSED ARE STILL APPLICABLE****Contact Information:**

Contact Name	Phone	Email	Comment
Janicek, Jake		JJanicek@caerusoilandgas.com	EHS Professional
Heil, John		john.heil@state.co.us	
Murray, Richard		g.richard.murray@state.co.us	
,		COGCC.inspections@caerusoilandgas.com	All Inspections
Fischer, Alex		alex.fischer@state.co.us	

**Inspected Facilities:**

Facility ID	Type	Status	Status Date	Well Class	API Num	Facility Name	Insp Status
470366	SPILL OR RELEASE	AC			-	F23-596 Dumpline Release	EI

**General Comment:**

COGCC Environmental inspection. Follow-up to operator's eForm 19 Spill/Release Report (doc #402269309) for Spill/Release ID #470366. Weather conditions during inspection were sunny skies with a temperature of 31 degrees Fahrenheit.

Operator's eForm 19 reports the release of approximately 43 bbls of produced water due to a failed dumpline. Flowline had been repaired prior to inspection. See photos.

**Location**Overall Good: ☐

Emergency Contact Number:

Comment: Corrective Action: Date: Overall Good: ☐**Spills:**

Type	Area	Volume		
------	------	--------	--	--

In Containment: No

Comment: ☐ Multiple Spills and Releases?**Tanks and Berms:**

Contents	#	Capacity	Type	Tank ID	SE GPS	
OTHER	3	300 BBLS	STEEL AST		,	
Comment:	<input type="text"/>					
Corrective Action:	<input type="text"/>				Date:	<input type="text"/>

**Paint**

Condition	
Other (Content)	(2) condensate, (1) produced water
Other (Capacity)	<input type="text"/>
Other (Type)	<input type="text"/>

**Berms**

Type	Capacity	Permeability (Wall)	Permeability (Base)	Maintenance
Metal	Adequate			Inadequate
Comment:	Multiple tears observed in northeast side of tank battery liner, near loadout. West side of secondary containment area was covered by a tarp on inspection date. See photos.			
Corrective Action:	Repair or install berms or other secondary containment devices per Rule 605.a.(4).			Date: 01/30/2020

**Venting:**

Yes/No	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

**Flaring:**

Type	<input type="text"/>	
Comment:	<input type="text"/>	
Corrective Action:	<input type="text"/>	Date: <input type="text"/>

**Inspected Facilities**Facility ID: 470366 Type: SPILL OR API Number: - Status: AC Insp. Status: EI**Attached Documents**You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
698100115	20191220 field photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5025069">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5025069</a>