


## Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



**Photo #0328 photo from entrance to location.**



**Photo #0334 access road has not been adequately maintained.**



## Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



**Photo #0330 weeds inside tank containment**



**Photo #0331 weeds around equipment.**

## Inspection Photos

Location Name: MARALEX RESOURCES INC SULFUR GULCH-69S98W /2SWSW

Location ID: 312662



Photo #0332 weeds around pump jack.