

Inspection Photos
Operator: Southland Royalty
Location/API #: 007-06211
Date: 12-30-2019



Photo 1. View of the project area from the eastern corner facing center.



Photo 2. View of the eastern project area from the eastern corner facing northwestward.



Photo 3. View of erosional channel where the southern sediment trap is breeched. This sediment trap does not have a stabilized overflow outlet.



Photo 4. View of the western project area from the southern corner facing northwestward.



Photo 5. View of reference area, comprised of pinyon and juniper woodland.