



**Location**

Overall Good:

<b>Signs/Marker:</b>			
Type	WELLHEAD		
Comment:	Adequate		
Corrective Action:		Date:	

Emergency Contact Number:

Comment:

Corrective Action:

Date: \_\_\_\_\_

Overall Good:

<b>Spills:</b>			
Type	Area	Volume	

In Containment: No

Comment:

Multiple Spills and Releases?

<b>Fencing/:</b>			
Type	WELLHEAD		
Comment:	Panel		
Corrective Action:		Date:	

<b>Equipment:</b>			corrective date
Type: Plunger Lift	# 1		
Comment:			
Corrective Action:		Date:	
Type: Bradenhead	# 1		
Comment:			
Corrective Action:		Date:	

<b>Venting:</b>			
Yes/No	NO		
Comment:			
Corrective Action:		Date:	

<b>Flaring:</b>			
Type			
Comment:			
Corrective Action:		Date:	

**Inspected Facilities**

Facility ID: 251385 Type: WELL API Number: 123-19188 Status: PR Insp. Status: SI

**Idle Well**

Purpose:  Shut In  Temporarily Abandoned Reminder: EQUIPMENT ONSITE

Comment: SI

Corrective Action:  Date:

**COGCC Comments**

Comment	User	Date
<p><b>THIS IS A FOLLOW UP INSPECTION TO PREVIOUS INSPECTION DOC#: 679601972.</b>                      All corrective actions assigned in previous inspection DOC#: 679601972 have been resolved. NO NEW corrective actions were observed at the time of re-inspection. Review my inspection, photos, and previous inspection DOC#: 679601972 for additional information on this location.                      **Weather Conditions: sunny, snow on ground</p>	santistb	01/02/2020

**Attached Documents**

You can go to COGCC Images (<https://cogcc.state.co.us/weblink/>) and search by document number:

Document Num	Description	URL
679602081	Photos	<a href="http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5026634">http://ogccweblink.state.co.us/DownloadDocumentPDF.aspx?DocumentId=5026634</a>